



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC23003361/Awy3e2 Date: 17/05/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 6874U	Veh. Inspected	GBJ 3523L
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC00/027197	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	30/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTFAT35Y40K212021	Colour	BLUE
	Odometer	150747 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	CONDOR	6 mm
	L/H Front Tyre	195 R15C	CONDOR	6 mm
	R/H Rear Tyre	155 R12C	CONDOR	6 mm
	L/H Rear Tyre	155 R12C	CONDOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/03/2023	Inspection Date	03/04/2023
	Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	