

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIANZ INSURAI	NCE SINGAPORE PTE LTD		Ref:	CS3/AIS23003364/y3	
	79 ROBINSON ROAD			Date:	31/03/2023	
	#09-01 SINGAPOF	RE 068897		Code:	AIC	
4		Policy Particulars :-	/TUDD DADTY			
1.	In a consul Made	1				
	Insured Veh.	GBB 9984S	Veh. Inspected		JPR 2656	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	SHANTI	Assign Date		30/03/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	ngine No. HIDDEN Year of Reg.				
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	28/03/2023	Inspection Dat	е		
	Survey held at	TRIPLE-T AUTOMOBILE				
		BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					