

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts E	n Automo		/LPC23000444
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC230	<del>)00444</del> /y3
	300 BEACH ROAD #17-04/07 THE CO	) DNCOURSESINGAPORE 199555		Date:	<del>13/01/2023</del>	31/03/2023
				Code:	LPC2	
	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 6675H	Veh. Inspected	d	SGU 291H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/026831	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		13/01/2023	31/03/2023
<u>.                                    </u>		Vehicle Partic	culars & Condit	ion		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre	<b>D</b> 1.0			mm	
	Description of Damages					
j.		Genera	I Information			
	Accident Date	10/01/2023	Inspection Da	te		
	Survey held at	SIN HENG LONG MOTOR WOR	DRK			
	BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535					
ia.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					