



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/III23001712/Rqy3-1	
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/III23001712/Rqy3 Date: 15/02/2023 29/03/2023 Code: III2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PA 911B	Veh. Inspected	GBC 4917P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JACELYN LOH	Assign Date	15/02/2023 29/03/2023
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/02/2023	Inspection Date	16/02/2023
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			