

QV F050

DPR LTR

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMC6291S

Make & Model: Volvo XC40

Chassis number: YV1XZ16ACK2045416

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ X 2,531.70
2	Bonnet insulator clips	1set	\$ X 80.00
3	Front bumper	1	\$ do 2,078.73
4	Front bumper clips	1set	\$ new 40 80.00
5	Front bumper rivets	1set	\$ new 30 70.00
6	Front bumper number plate holder	1	\$ X 66.80
7	Front bumper lower spoiler	1	\$ cut 615.68
8	Front bumper lower centre garnish	1	\$ X 780.19
9	Front bumper RH side garnish	1	\$ X 76.05
10	Front bumper LH side garnish	1	\$ X 76.05
11	Front bumper LH PDC sensor	1	\$ X 215.50
12	Front bumper centre bracket	1	\$ X 85.68
13	Front bumper reinforcement	1	\$ X 1,399.77
14	Front bumper RH side beam	1	\$ X 159.03
15	Front bumper LH side beam	1	\$ X 159.03
16	Front bumper centre beam	1	\$ X 96.57
17	Front bumper inner sponge	1	\$ X 310.48
18	RH headlamp assy	1	\$ X 3,055.80
19	LH headlamp assy	1	\$ new 3,055.80
20	Front grille	1	\$ cut 911.34
21	Front grille clips	1set	\$ new 30 80.00
22	Front grille emblem	1	\$ new 103.00
23	Aircon condenser frame support	1	\$ X 169.87
24	Aircon condenser	1	\$ X 973.90
25	Radiator assy	1	\$ X 690.18

\$ 17,921.15

Parts less 10% \$ 1,792.12

Total \$ 16,129.04

No.	Special Nett Items	Qty	Amount S\$
1	Front number plate	1	\$ X 80.00
2	Radiator coolant	1	\$ X 80.00
		Total:	\$ 160.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	250 \$ 1,400.00
2	Spray painting on affected areas and panels	250 \$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ X 80.00
5	Refocus and adjust headlamps assy	\$ 30 80.00
6	Remove and replace aircon condenser and pipes to assist repair	\$ X 280.00
7	Remove and replace radiator assy and hoses to assist repair	\$ X 280.00
Total:		\$ 3,400.00

Tanflin 9749 5747/62565581

WP, 11/4/15e 2pm

L/S Resing after repair

Tanflin e/Manito.com

- To check consistency of accident
- To check part prices

3 days

Spare Parts: \$ 16,129.04

Special Nett: \$ 160.00

Labour: \$ 3,400.00

Total Amount: \$ 19,689.04