

QV F050

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMC6291S

Make & Model: Volvo XC40

Chassis number: YV1XZ16ACK2045416

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ X ^{un} 2,531.70
2	Bonnet insulator clips	1set	\$ X ^{un} 80.00
3	Front bumper	1	\$ do 2,078.73
4	Front bumper clips	1set	\$ un ⁴⁰ 80.00
5	Front bumper rivets	1set	\$ un ³⁰ 70.00
6	Front bumper number plate holder	1	\$ X ^{un} 66.80
7	Front bumper lower spoiler	1	\$ cut 615.68
8	Front bumper lower centre garnish	1	\$ X ^{un} 780.19
9	Front bumper RH side garnish	1	\$ X ^{un} 76.05
10	Front bumper LH side garnish	1	\$ X ^{un} 76.05
11	Front bumper LH PDC sensor	1	\$ X 215.50
12	Front bumper centre bracket	1	\$ X 85.68
13	Front bumper reinforcement	1	\$ X 1,399.77
14	Front bumper RH side beam	1	\$ X 159.03
15	Front bumper LH side beam	1	\$ X 159.03
16	Front bumper centre beam	1	\$ X 96.57
17	Front bumper inner sponge	1	\$ X 310.48
18	RH headlamp assy	1	\$ X 3,055.80
19	LH headlamp assy	1	\$ cut 3,055.80
20	Front grille	1	\$ cut 911.34
21	Front grille clips	1set	\$ un ³⁰ 80.00
22	Front grille emblem	1	\$ un ³⁰ 103.00
23	Aircon condenser frame support	1	\$ X 169.87
24	Aircon condenser	1	\$ X 973.90
25	Radiator assy	1	\$ X 690.18

6069.55

5462.41

	\$	17,921.15
Parts less 10%	\$	1,792.12
Total	\$	16,129.04

No.	Special Nett Items	Qty	Amount S\$
1	Front number plate	1	\$ X ^{un} 80.00
2	Radiator coolant	1	\$ X ^{un} 80.00
	Total:		\$ 160.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	250 \$ 1,400.00
2	Spray painting on affected areas and panels	250 \$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ X 80.00
5	Refocus and adjust headlamps assy	\$ 30 80.00
6	Remove and replace aircon condenser and pipes to assist repair	\$ X 280.00
7	Remove and replace radiator assy and hoses to assist repair	\$ X 280.00
Total:		\$ 3,400.00

560

Tanah 9749 5747/62565561

WP 11/4/250 2pm

L/S Resing after repair

tanah c/haute.com

- To check consistency of accident

- To check part prices

3 days

Spare Parts: \$ 16,129.04
Special Nett: \$ 160.00
Labour: \$ 3,400.00

Total Amount: \$ 19,689.04

5462.41

560

6022.41

4800

3 days #