



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23003377/Kqp3m4	
			Date: 12/05/2023	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLB 8646G	Veh. Inspected	SJY 3006P
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS23/0246	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	30/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN TOURAN TSI (A)	c.c	1390
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WVGZZZ1TZAW109531	Colour	METALLIC SILVER
	Odometer	235505 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	FIRENZA	7 mm
	L/H Front Tyre	225/45 R17	FIRENZA	7 mm
	R/H Rear Tyre	225/45 R17	FIRENZA	7 mm
	L/H Rear Tyre	225/45 R17	FIRENZA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/03/2023	Inspection Date	30/03/2023
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)REGISTRATION DATE: 18 AUG 2010 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	