

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Ezlyna.

DATE : 20.03.2023

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNH956J**
MODEL : **VOLKSWAGEN GOLF**
DATE OF ACCIDENT : 07.03.2023
TIME OF ACCIDENT : 19:15 HOURS

NVW222Au214 W099467

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE TOP LOCK	1	\$ 388.54	\$ 388.54
2	TAILGATE LOWER LOCK	1	\$ 568.75	\$ 568.75
3	TAILGATE WEATHESTRIIP	1	\$ 635.60	\$ 635.60
4	TAIL LAMP	2	\$ 833.51	\$ 1,667.02
5	REAR BUMPER	1	\$ 1,588.40	\$ 1,588.40
6	REAR BUMPER DIFFUSER	1	\$ 498.50	\$ 498.50
7	REAR BUMPER REFLECTOR	2	\$ 180.17	\$ 360.34
8	REAR BUMPER NUMBER PLATE LAMP	2	\$ 99.87	\$ 199.74
9	REAR BUMPER CORNER BRACKET	2	\$ 168.30	\$ 336.60
10	REAR BUMPER CENTER BEAM	1	\$ 395.60	\$ 395.60
11	REAR BUMPER SIDE BRACKET	2	\$ 198.50	\$ 397.00
12	REAR BUMPER REINFORCEMENT	1	\$ 659.46	\$ 659.46
13	REAR FENDER INNER TRIM	2	\$ 535.60	\$ 1,071.20
14	REAR FENDER COWLING	2	\$ 158.30	\$ 316.60
15	REAR END PANEL	1	\$ 1,599.60	\$ 1,599.60
16	REAR END PANEL TOP GARNISH	1	\$ 346.87	\$ 346.87
17	REAR FLOOR MAT	1	\$ 398.69	\$ 398.69
18	REAR FLOOR PANEL TOP BOARD	1	\$ 698.75	\$ 698.75
19	REAR TOOLS SPONGE	1	\$ 189.98	\$ 189.98

TOTAL PRICE \$ 12,317.24
LESS 10% \$ 1,231.72

4439.14

3995.22

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNH956J**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 07.03.2023
 TIME OF ACCIDENT : 19:15 HOURS

SUB TOTAL PRICE \$ 11,085.52

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>rw</i>	1	\$ 80.00	\$ 80.00
3	REAR FENDER INNER TRIM CLIPS (SET) <i>3rd</i>	1	\$ 80.00	\$ 80.00
4	REAR FENDER COWLING CLIP <i>rw</i>	1	\$ 40.00	\$ 40.00
5	TAILLAMP CLIP (SET) <i>rw</i>	1	\$ 50.00	\$ 50.00
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>rw</i>	1	\$ 30.00	\$ 30.00
7	REAR END PANEL INSULATION SEAL <i>rw</i>	1	\$ 150.00	\$ 150.00
8	REVERSE CAMERA <i>Dund</i>	1	\$ 550.00	\$ 550.00
9	REVERSE SENSOR <i>Dund</i>	1	\$ 220.00	\$ 220.00

810

TOTAL \$ 1,250.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	400
3	TUFF COAT	\$ 250.00	40
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNH956J**
MODEL : **VOLKSWAGEN GOLF**
DATE OF ACCIDENT : 07.03.2023
TIME OF ACCIDENT : 19:15 HOURS

8	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 180.00	50
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 380.00	X

1230

TOTAL \$ 4,500.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,335.52
TOTAL LABOUR COST : \$ 4,500.00
TOTAL REPAIR COST : \$ 16,835.52

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP:8297 9787

total: 6035.22
L/S! 4.8K

4.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: