

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23003383/KPA3Q2**Date:** 20/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_02

Claimant Vehicle No : PC6565S **Insured Vehicle No :** SNJ9873U

Date of Loss: 30/03/2023 Nature of Claim: TP Claim No: MFL2023D0003559

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC6565S**
 Make & Model: MERCEDES-BENZ VIANO CDI, 2.1 D EL (A) Engine No: 65194030943404
 Reg. Date: 25/04/2012 (Man. Year: 2011) Chassis No: WDF63981523715499
 Colour: Black Odometer: 663157 km
 Engine Capacity: 2143 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16
 Front Left Side: Habilead 9 mm Rear Left Side: Habilead 9 mm
 Front Right Side: Habilead 9 mm Rear Right Side: Habilead 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	0.00	3,800.00	-3,800.00	
+ GST 8.00/8.00% (S\$)	0.00	304.00	-304.00	
Nett Amount (S\$)	0.00	4,104.00	-4,104.00	
+ Loss of Use (5.0 x S\$130.00/day) (S\$)		650.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		4,780.75		

INSPECTION

Date of Assignment: 31/03/2023

Date Inspected: 31/03/2023 Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	143	MERCEDES-BENZ VIANO CDI 2.1 D EL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6565S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >