

ASS. REC. BY:

REF:

TE / 23 003383/kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 835k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 04/27 Vehicle: IN / OUT

Person Contacted: _____

Veh No: PC 65855 Yr Regn: 04/12Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Mer Viano C.C. 2143Colour: Black A/C: Insured / Std / NI / NASp. Reading: 663157 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF-63981523715499Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habited

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 30/3/23 D.O.I. 31/3/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRM O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/4 21km 838000 Caravan

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SNJ9873U
Accident Date : 30-Mar-2023

Our Ref : 023070 (III) / CHAN

FAIRWAY LIMOUSINE NETWORK PTE LTD
BLK 155 SIMEI ROAD
#02-206
Singapore 520155

No. : 06797

Date : 30-Mar-2023

PAGE : 1

*Not Withheld
11 Sep @ 3800.
Resurvey After Paint
4 days*

ESTIMATED COST OF REPAIR FOR M/BENZ VIANO CDI2.2EL PC6565S

1 pc O/s headlamp *2052*
1 pc Front o/s fender
1 pc Front bumper fascia
1 pc Front bumper reinforcement
1 pc Front o/s bumper side retainer
1 pc Front o/s bumper lower grille
1 pc Front bumper ctr lower grille
1 pc Front grille

CM 2,058.00 ✓
Bu 774.00 ✓
Bu 1,092.00 ✓
R 969.00 ✗
Dis 68.00 ✓
AL 58.00 ✓
Sn 78.00 ✗
Sn 459.00 ✗

5,556.00

Less 10% : 555.60

1 pc Front no.plated with box

CM 5,000.40 *45sn*
CM 50.00 *sn*

To putty and spray replaced parts

700.00 *600d*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *45d*

To rewire damaged parts and refocus
headlamp beam.

60.00 *2d*

Total : S\$ 6,410.40

Singapore Dollars Six Thousand Four Hundred and
Ten and Cents Forty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by, repairer
Signature: