

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SNJ9873U
Accident Date : 30-Mar-2023

Our Ref : 023070 (III) / CHAN

FAIRWAY LIMOUSINE NETWORK PTE LTD
BLK 155 SIMEI ROAD
#02-206
Singapore 520155

No. : 06797

Date : 30-Mar-2023

PAGE : 1

Not Withoin
1/1 Sup &
Mervey After Paint

ESTIMATED COST OF REPAIR FOR M/BENZ VIANO CDI2.2EL PC6565S

1 pc O/s headlamp
1 pc Front o/s fender
1 pc Front bumper fascia
1 pc Front bumper reinforcement
1 pc Front o/s bumper side retainer
1 pc Front o/s bumper lower grille
1 pc Front bumper ctr lower grille
1 pc Front grille

CM 2,058.00 ✓
Bu 774.00 ✓
Bu 1,092.00 ✓
969.00 ?
Di 68.00 ✓
M 58.00 ✓
78.00 ?
459.00 ?

5,556.00

Less 10% : 555.60

1 pc Front no.plated with box

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

To rewire damaged parts and refocus
headlamp beam.

5,000.40 *65 sn*
CM 50.00 sn

700.00 *600*

600.00 *450*

60.00 *20*

Total : S\$ 6,410.40

Singapore Dollars Six Thousand Four Hundred and
Ten and Cents Forty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by repairer