

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23003384/SQP3Q2**Date:** 15/05/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000390	
Claimant Vehicle No :	SH7346P	Insured Vehicle No :	GBE4810C	
Date of Loss:	30/03/2023	Nature of Claim:	TP	Claim No: M2302126

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7346P	Engine No:	D4FDGU701158
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU097339
Reg. Date:	29/12/2016 (Man. Year: 2016)	Odometer:	928150 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,075.84	4,265.68	1,810.16	29.79
Miscellaneous Items	211.00	211.00	0.00	0.00
Labour	2,140.00	1,750.00	390.00	18.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,426.84	6,226.68	2,200.16	26.11
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	8,426.84	5,000.00	3,426.84	40.67
+ GST 8.00/8.00% (S\$)	674.15	400.00	274.15	40.67
Nett Amount (S\$)	9,100.99	5,400.00	3,700.99	40.67

INSPECTION

Date of Assignment:	31/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	31/03/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7346P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Buckled	663.00 FL	*663.00 FL
2	1		*FENDER RETAINER LH	Not Necessary	24.60 FL	*- FL
3	1		*HEADLAMP LH	Not Necessary	1,388.00 FL	*- FL
4	1		*FRONT BUMPER COVER	Cracked	1,052.20 FL	*1,052.20 FL
5	1		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*FRT BUMPER SIDE BRACKET LH	Not Necessary	24.60 FL	*- FL
7	1		*FRT WHEEL HUB CAP LH	Cracked	217.20 FL	*217.20 FL
8	1		*FRT DOOR LH	Buckled	2,707.70 FL	*2,707.70 FL
9	1		*FRT DOOR MIRROR LH	Cracked	670.00 FL	*670.00 FL
10	1		*FRT FENDER SHIELD LH	Not Necessary	174.90 FL	*- FL
11	1		*FRT WHEEL RIM LH	Not Necessary	650.60 FL	*- FL
					Sub Total (S\$)	7,594.80 5,332.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,518.96 1,066.42
					Total Parts (S\$)	6,075.84 4,265.68

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	RENEW ADVERTISEMENT STICKER (Necessary)	200.00	200.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			211.00	211.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	900.00
2	SPRAY PAINTING CHARGE	New	1,000.00	750.00
3	TRANSFER OF DOOR	New	120.00	40.00
4	TUFF KOTE	New	60.00	30.00
5	CHECK ALL LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			2,140.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >