



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |  |  |
|--|---|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909   |   |                 | Ref: CS3/CTI22009690/Svp3e2-1<br>Date: 10/07/2023<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>  |   |                 |  |  |
| Insured Veh.   | SMD 4909C   | Veh. Inspected  | SMQ 5030L  |  |
| Policy No.   | DMPCSNW00184692202  | Coverage (\$)   | 0.00   |  |
| Claim No.  | SNM22D206855/C02/KHONGL<br>H  | Excess (\$)     | 0.00   |  |
| Assign From  | LYNN KHONG  | Assign Date     | 30/03/2023   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |  |  |
| Make & Model   | MERCEDES BENZ A180  | c.c             | 1595   |  |
| Engine No.   | HIDDEN  | Year of Reg.    | 2017   |  |
| Chassis No.  | WDD1760422J594726   | Colour          | YELLOW   |  |
| Odometer   | -   | Steering        | IN ORDER   |  |
| Brakes   | IN ORDER  | Modification    | SPORTS RIM   |  |
| General  | FAIR  |                 |  |  |
| <b>3. Conditions of Tyres</b>  |   |                 |  |  |
|  | Size  | Make            | Balance  |  |
| R/H Front Tyre   | 225/40 R18  | MICHELIN        | 6 mm   |  |
| L/H Front Tyre   | 225/40 R18  | MICHELIN        | 6 mm   |  |
| R/H Rear Tyre  | 225/40 R18  | MICHELIN        | 6 mm   |  |
| L/H Rear Tyre  | 225/40 R18  | MICHELIN        | 6 mm   |  |
| <b>4. Description of Damages</b>   |   |                 |  |  |
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.<br>REPAIR CONDITION SEE DETAILS.   |   |                 |  |  |
| <b>5. General Information</b>  |   |                 |  |  |
| Accident Date  | 23/09/2022  | Inspection Date | 26/05/2023   |  |
| Survey held at   | NXPRESS PERFORMANCE PTE LTD<br>25 KAKI BUKIT ROAD 4, #01-39, SYNERGY @ KB, SINGAPORE 417800 |                 |  |  |
| <b>5a. Remarks</b>   |   |                 |  |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |  |  |
| <b>5b. Estimate Days of Repair</b>   |   |                 |  |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   |                 | 14 Working Days  |  |