

ASTUTE AUTOWORKS

60 JALAN LAM HUAT #02-16/17 (CARROS CENTRE) SINGAPORE 737869
6530 3611 | ASTUTE.COM.SG | 6530 3711

Estimate Repair List

10 Apr 2023

United Overseas Insurance
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Attn: Motor Claims Department

Not in the car AAPL Claims23-11

61 Day @ 2500h
Recovery After Repair
4 1/2 days

Kennoch
98910663

ACCIDENT INVOLVING SNG 1638 B & YN 5288 J ON 27.03.2023 ALONG WOODLANDS SPECTRUM 1 AT ABOUT 1000 HOURS

Insured : Cheong Kong Chuan
Vehicle Registration No : SNG 1638 B
Vehicle Make : Renault
Vehicle Model : Scenic IV 1.5L DCI AT EU6
Vehicle Chassis No : VF1RFA00361137060
Policy No : 5126849559
Date of Accident : 27.03.2023

S/N	Quantity	Description	Type of Claim: 3rd Party	
			Unit Price S\$	Amount S\$
1	1	Front bumper <i>1557</i>	<i>cm</i>	\$ 1,660.20 <i>—</i>
2	10	Front bumper clips	\$ <i>mc</i> 3.90	\$ 39.00 <i>—</i>
3	1	Front grille	<i>cm</i>	\$ 586.25 <i>—</i>
4	1	Front emblem	<i>m</i>	\$ 135.50 <i>—</i>
				\$ 2,420.95
			Less 6% <i>10%</i>	\$ (121.05)
				\$ 2,299.90
Front bumper proximity sensor			<i>cn</i>	\$ 200.00 <i>—</i>

Dismante and change front bumper proximity sensor, front bumper, front grille, knocking front bonnet and realign front portion

\$ 800.00 *900 400*

To do wire checking

\$ 50.00 *20*

To spray front bumper and front bonnet

\$ 600.00 *440*

\$ 3,949.90

8% GST \$ 315.99

Total \$ 4,265.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Claims Dept
Mrs Tan @ 9639 9195

Acknowledged by Repairer

Signature:

Date: