

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

LIM SHEN

BLK 483 ADMIRALTY LINK #12-35

SINGAPORE 750483

TAX INVOICE

Repair Code : CLM15853

Date in : 30/03/2023

Vehicle Num. : SMR2414C

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72001614/LEB7102245

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	1150.00	1050 1,150.00
REAR BUMPER REFLECTOR GARNISH L/R <i>LH cracked</i>	2	45.00	45 90.00
REAR BUMPER REFLECTOR L/R <i>RH cracked</i>	2	45.00	45 90.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	26.50	x 53.00
REAR BUMPER SPONGE L/R <i>LH cracked</i>	2	89.50	89.50 179.00
REAR BUMPER UNDER COVER LH <i>3 new</i>	1	98.30	x 98.30
REAR BUMPER UNDER COVER RH <i>new</i>	1	95.20	x 95.20
REAR END PANEL <i>Repair</i>	1	560.80	x 560.80
REAR END PANEL INNER TOP GARNISH <i>cracked</i>	1	155.50	✓ 155.50
REAR FLOOR PANEL COMPARTMENT TRAY <i>new</i>	1	368.00	x 368.00
REAR LH FENDER INNER TRIM GARNISH <i>new</i>	1	468.20	x 468.20
REAR TAILGATE <i>Dented</i>	1	1193.00	✓ 1,193.00
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	75.80	✓ 75.80
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	38.00	+ 38.00
REAR TAILGATE 'SHUTTLE' EMBLEM <i>new</i>	1	55.00	✓ 55.00
REAR TAILGATE HINGES L/R <i>3 new</i>	2	50.00	x 100.00
REAR TAILGATE INNER PULL HANDLE	1	25.00	x 25.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	18.50	x 37.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LIM SHEN
 BLK 483 ADMIRALTY LINK #12-35
 SINGAPORE 750483

Contact : 91177007

TAX INVOICE

Repair Code : CLM15853

Date in : 30/03/2023

Vehicle Num. : SMR2414C

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72001614/LEB7102245

REAR TAILGATE INNER TRIM BOARD <i>cracked</i>	1	320.00	✓	320.00
REAR TAILGATE LOCK STRIKER <i>new</i>	1	27.50	✗	27.50
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	157.10	✓	157.10
REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH <i>Not new</i>	1	383.10	✗	383.10
REAR TAILGATE REFLECTOR INNER RUBBER GASKET L/R <i>Not new</i>	2	25.00	✗	50.00
REAR TAILGATE REFLECTOR L/R <i>Not new</i>	2	411.00	✗	822.00
REAR TAILGATE WEATHER STRIP <i>Not</i>	1	168.50	✓	168.50
REAR TAILGATE WINDSCREEN MOULDING <i>Not</i>	1	120.00	✓	120.00
Subtotal before discount				6,880.00
Percentage discount 20%				1,376.00
Sub-total 1				5,504.00
REAR BUMPER CLIPS - SET <i>Not</i>	1	80.00	30 ✓	80.00
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	1	280.00	200 ✓	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Not</i>	1	50.00	10 ✓	50.00
REAR LH FENDER INNER TRIM GARNISH CLIPS - SET <i>Not new</i>	1	50.00	✗	50.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Not</i>	1	40.00	30 ✓	40.00
REAR TAILGATE NUMBER PLATE <i>Not new</i>	1	25.00	✗	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>Not new</i>	1	50.00	✗	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM SHEN
BLK 483 ADMIRALTY LINK #12-35
SINGAPORE 750483

Contact : 91177007

TAX INVOICE

Repair Code : CLM15853

Date in : 30/03/2023

Vehicle Num. : SMR2414C

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72001614/LEB7102245

REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH CLIPS - SET	330	30.00	x	30.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00
Subtotal before discount				685.00
Percentage discount 0%				0.00
Sub-total 2				685.00
Parts-total				6,189.00

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,670.00
Parts & Labour Total	8,859.00

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey (before/after spray painting)
- To display (damaged part(s)) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
L/S 20/04/23.

04 Days'

total: 4689.52
L/S: 3750