

ASS. REC. BY:

REF:

A15/ 230034061ky

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

SMRT

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SG 5969K

Yr Regn:

10.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mar Ng 363f

c.c

10518

Colour

Green

A/C: Insured / Std / NI / NA

Sp. Reading

272285

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WM AA 95 22 4 JF 007009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

275/70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

R/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

28/3/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/4 21 Rg &amp; 2200d Car

Data/Time, File Pass to?



: Prell. Report

1)

Data/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

**SMRT Accident Vehicle Repair Estimates**

|   |
|---|
| <b>SMRT Automotive Services Pte Ltd</b>           |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |


Date Generated : 30/03/2023

User ID : GohKK2

**Section A - Accident Details**

|                                    |  |
|------------------------------------|--|
| Registration Number                | SG5969K  |
| Case Reference Number              | BUS/03/23/7026   |
| Registration Date                  | 18/10/2018   |
| Company Type                       | SMRT Buses Ltd   |
| Make                               | MAN  |
| Model                              | MAN A95  |
| Name of Driver                     | Wang Zhaojin   |
| Type of Accident                   | Side Swipe   |
| Accident Date and Time             | 28/3/2023 6:55 PM  |
| Accident Reported Date and Time    | 29/3/2023 2:52 PM  |
| Is Surveyor Required?              | Yes  |
| Survey by                          |  |
| Vehicle is Towed Back?             | No   |
| Towed Back Date and Time           |  |
| Replacement Vehicle Issued?        | No   |
| Job Card Number                    |  |
| Special Instruction to ARC, if any | SG5969K - REAR RIGHT PORTION<br>SMW5859G (TP) - INSURED WITH ALLIANZ |
| Prepared Date and Time             | 30/3/2023 2:29 PM  |
| Chassis Number                     | WMAA95ZZ4JF007009  |
| Mileage                            |  |
| Work Shop                          |  |
| Repair Completion Date and Time    |  |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |   |                                     |
|------------------------------|---|-------------------------------------|
|                              | Quotation from ARC  | Adjusted by Surveyor, if applicable |
| Total Labour Cost            | \$795.00  | \$0.00                              |
| Total Spray Cost             | \$538.00  | \$0.00                              |
| Total Spare Part Cost        | \$2,084.98  | \$0.00                              |
| Total Other Cost             | \$0.00  | \$0.00                              |
| <b>TOTAL COST</b>            | <b>\$3,417.98</b>   | <b>\$0.00</b>                       |
| Lump Sum Total               | \$3,400.00  | \$0.00                              |
| Number of Repair Days        | 3.0   | 2 days                              |
| Prepared / Adjusted By       | ARC Manager Team  |                                     |
| ARC / Surveyor Sign Off Date | 30/03/2023 2:35 PM  |                                     |
| Signature                    |  | Kenneth (Chik)                      |
| Remarks                      |   |                                     |

**Section C - Quotation and Accident Invoice Details**

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |



**SMRT Accident Vehicle Repair Estimates**

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 30/03/2023

User ID : GohKK2

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

| Job Scope  | Quotation from AR | Adjusted by Surveyor, if applicable |
|--|-------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS | \$795.00          | 530                                 |
| <b>Total Labour</b>  | <b>\$795.00</b>   |                                     |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | \$538.00           | 432                                 |
| <b>Total Spray Painting &amp; Panel Beating</b>                     | <b>\$538.00</b>    |                                     |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| Job Scope                | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------|--------------------|-------------------------------------|
| <b>Total Other Costs</b> |                    |                                     |

**Part 4 - Spare Parts / Material Usage**

| Part Number  | Portion | Stock Number    | Part Name                   | Quantity | List Price (\$)   | Discount (%) | Final Price (\$)  | Estimator Approved | Surveyor Approved |
|--------------|---------|-----------------|-----------------------------|----------|-------------------|--------------|-------------------|--------------------|-------------------|
| 6012635      | VE      |                 | REAR LAMP BULB (A95 MAN)    | 1.00     | \$245.00          | 10.00        | \$220.50          | Replace            | AR See X          |
| 6012636      | VE      |                 | REVERSE LAMP BULB (A95 MAN) | 1.00     | \$235.00          | 10.00        | \$211.50          | Replace            | CM ✓              |
| 6010298      |         |                 | STOP LAMP LED               | 1.00     | \$1,141.70        | 10.00        | \$1,027.53        | Replace            | AR X              |
| 6010299      |         |                 | SIGNAL LAMP LED             | 1.00     | \$1,274.10        | 10.00        | \$1,146.69        | Replace            | CM ✓              |
| 6013482      | Body    | 124-2-2-009-012 | O/S FRP REAR LAMP           | 1.00     | \$975.00          | 100.00       | \$0.00            | Repair             |                   |
| <b>Total</b> |         |                 |                             |          | <b>\$3,870.80</b> |              | <b>\$2,606.22</b> |                    |                   |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|--------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| <b>Total</b> |         |              |           |          |               |              |                  |           |                |

NOT WITHIN  
L1P & 220d  
Penny After Paint

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: