



Not Notified
Resurvey B4 paint
4 days

Auto 101 LLP

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01

Singapore 768159

Tel: 67545101

DATE: 10-4-2023

REPAIR ESTIMATE

VEHICLE: SNC 4579 P
MODEL: Peugeot 2008

S/n	Description of part	Qty	Estimate	
1	Rear bumper	1	Bu 2,340.00	✓
2	Rear bumper clip - set	1	ru 40.00	✓
3	Reverse sensor	1	2 sen 1,120.00	4
4	emblem "2008"	1	ru 68.00	✓
5	Rear tailgate logo	1	ru 68.00	✓
6	Rear bumper reinforcement	1	625.00	?
7	Rear bumper center bracket	1	410.00	?
8	Rear bumper center retainer	1	R 365.00	?
9	Rear bumper side retainer LH/RH	2	ru 372.00	X
10	Rear bumper lower water shield	1	580.00	?
11	Rear bumper lower water shield clip set	1	30.00	?
12	Rear bumper top garnish	1	ru 460.00	✓
13	exhaust muffler	1	1,410.00	?
14	Exhaust chrome garnish LH/RH	2	ru 460.00	✓
Sub-total 1			7,372.00	
Discount 10%			6,634.80	
15	Car number plate rear	1	ru 50.00	45 ru
Sub-total 2			50.00	
Parts total			6,684.80	
Labour				
16	To straighten and panel beating rear frame members. To remove and refit above parts.		1,000.00	400
17	To putty, re-spray painting and polish affected rear areas.		900.00	400
18	To check and rectify wiring system.		80.00	20
19	Remove and replace exhaust		150.00	?
20	To rust proof affected areas.		ru 60.00	X
Labour total			2,190.00	
Parts & Labour total			8,874.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: