

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

: ZVW301907393

TP China
Xiao Teng

CLAIM DETAILS: PARTS		QTY	UNIT PRICE	TOTAL
1	FRONT NUMBER PLATE GARNISH <i>Dehd</i>	1	\$ 99.60	\$ 99.60
2	FRONT BUMPER <i>Dehd.</i>	1	\$ 1,230.40	\$ 1,230.40
3	FRONT BUMPER SIDE HOLDER <i>New</i>	2	\$ 45.60	\$ 91.20
4	FRONT BUMPER SIDE LAMP <i>Not new</i>	2	\$ 128.20	\$ 256.40
5	FRONT BUMPER TOW COVER <i>Dehd</i>	2	\$ 38.10	\$ 76.20
6	FRONT BUMPER LOWER GRILLE <i>Dehd</i>	1	\$ 278.90	\$ 278.90
7	FRONT BUMPER LOGO <i>New</i>	1	\$ 68.50	\$ 68.50
8	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 529.40	\$ 529.40
9	FRONT BUMPER SPONGE <i>could</i>	1	\$ 172.50	\$ 172.50
10	FRONT BUMPER AIR GRILLE <i>Not new</i>	2	\$ 75.20	\$ 150.40
11	HEADLAMP (HID) <i>Cracked.</i>	2	\$ 1,740.40	\$ 3,480.80
12	FRONT SUPPORT PANEL <i>Repair</i>	1	\$ 1,058.40	\$ 1,058.40
13	FRONT SUPPORT PANEL TOP GARNISH <i>Dehd</i>	1	\$ 190.70	\$ 190.70
14	OIL COOLER <i>3 HP</i>	1	\$ 872.50	\$ 872.50
15	AIR CON CONDENSER <i>3 New</i>	1	\$ 1,290.40	\$ 1,290.40
16	BONNET <i>3 HP</i>	1	\$ 945.10	\$ 945.10
17	BONNET LOCK <i>3 New</i>	1	\$ 201.70	\$ 201.70
18	REAR BUMPER <i>Distorted</i>	1	\$ 1,218.30	\$ 1,218.30
19	REAR BUMPER SIDE HOLDER <i>Dnd</i>	2	\$ 58.20	\$ 116.40
20	REAR END PANEL <i>Dented</i>	1	\$ 781.70	\$ 781.70
21	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 374.10	\$ 374.10
22	TAILLAMP <i>could</i>	2	\$ 548.40	\$ 1,096.80
23	TAILLAMP BRACKET <i>could.</i>	2	\$ 50.50	\$ 101.00
24	TAILLAMP PANEL <i>LH Dented</i>	2	\$ 283.40	\$ 566.80
25	TAILGATE <i>Dented</i>	1	\$ 1,345.10	\$ 1,345.10
26	TAILGATE LOCK <i>Damaged</i>	1	\$ 374.90	\$ 374.90
27	TAILGATE WEATHERSTRIPE <i>lt</i>	1	\$ 355.10	\$ 355.10
28	TAILGATE INNER TRIM COVER <i>new</i>	1	\$ 481.10	\$ 481.10
29	TAILGATE LOWER GLASS C/W MOULDING <i>new</i>	1	\$ 988.40	\$ 988.40
30	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 182.90	\$ 182.90
31	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 722.10	\$ 722.10
32	TOYOTA LOGO <i>3</i>	1	\$ 68.50	\$ 68.50
33	PRIUS WORDING <i>Not nec</i>	1	\$ 58.10	\$ 58.10
34	HYBRID EMBLEM <i>3</i>	1	\$ 65.60	\$ 65.60
35	REAR FENDER <i>RH Buckled.</i>	2	\$ 972.60	\$ 1,945.20
36	REAR FENDER INNER SHIELD <i>new</i>	2	\$ 180.20	\$ 360.40
37	REAR FENDER INNER TRIM COVER <i>RH Crumpled</i>	2	\$ 307.10	\$ 614.20
38	REAR FENDER GLASS C/W MOULDING <i>RH New</i>	2	\$ 485.40	\$ 970.80

39	SPARE TYRE PANEL <i>Buckled</i>	1	\$	1,105.80	\$	1,105.80	✓
40	SPARE TYRE PANEL TOP BOARD <i>dehnd</i>	1	\$	542.10	\$	542.10	✓
41	SPARE TYRE PANEL TOOLS TRAY SPONGE <i>cracked</i>	1	\$	541.40	\$	541.40	✓
42	SPARE TYRE PANEL LOCK SCREW <i>new</i>	1	\$	39.40	\$	39.40	✓
43	SPARE TYRE PANEL BASE SPONGE <i>cracked</i>	1	\$	124.70	\$	124.70	✓
44	SPARE TYRE PANEL UNDERCOVER <i>dehnd</i>	1	\$	298.40	\$	298.40	✓
45	REAR EXHAUST PIPE <i>Repair</i>	1	\$	899.20	\$	899.20	✓
46	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$	38.40	\$	38.40	✓
47	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$	35.90	\$	35.90	✓
48	REAR EXHAUST PIPE HEAT SHIELD <i>crumpled</i>	1	\$	122.20	\$	122.20	✓
49	REAR DOOR <i>Repair</i>	2	\$	1,547.60	\$	3,095.20	✓
50	REAR DOOR LOCK <i>3 new</i>	2	\$	348.10	\$	696.20	✓
51	REAR DOOR WEATHERSTRIPE <i>new</i>	2	\$	290.60	\$	581.20	✓

TOTAL PRICE: \$ 31,900.70
 LESS 25% \$ 7,975.17
 SUB TOTAL PRICE: \$ 27,522.56

16668.10

12501.07

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT NUMBER PLATE <i>cracked</i>	1	\$ 30.00	\$ 30.00	✓
2	FRONT NUMBER PLATE HOLDER <i>dehnd</i>	1	\$ 30.00	\$ 30.00	✓
3	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
5	REAR NUMBER PLATE <i>3 new</i>	1	\$ 30.00	\$ 30.00	✓
6	REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00	✓
7	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
8	REVERSE SENSOR <i>Dehnd</i>	1 SET	\$ 280.00	\$ 280.00	✓
9	RAER END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
10	RAER END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
11	TAILGATE INNER TRIM COVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
12	TAILGATE TOP SPOILER <i>Repair</i>	1	\$ 1,200.00	\$ 1,200.00	✓
13	TAILGATE LOWER GLASS SEALANT <i>3 new</i>	1 SET	\$ 50.00	\$ 50.00	✓
14	TAILGATE GLASS SEALANT	1 SET	\$ 60.00	\$ 60.00	✓
15	REAR FENDER INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
16	REAR FENDER INNER TRIM COVER CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
17	REAR FENDER GLASS SEALANT <i>new</i>	2 SET	\$ 50.00	\$ 100.00	✓
18	SPARE TYRE PANEL UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
19	REAR DOOR BLACK TAPE <i>new</i>	2 SET	\$ 60.00	\$ 120.00	✓

TOTAL : \$ 2,270.00

630

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 3,800.00	2000	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 3,000.00	1500	
3	WIRING CHECK	\$ 150.00	60	
4	TO APPLY TUFF COAT	\$ 200.00	100	
5	TO REMOVE CONDENSER & TOP UP AIR CON GAS	\$ 120.00	X	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	X	
7	TO REMOVE UPHOLSTERY & REAR SEAT	\$ 300.00	180	
8	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
9	TO REMOVE FUEL TANK	\$ 150.00	X	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	120	

11	TO REMOVE TAILGATE LOWER GLASS	\$	150.00	80	
12	TO TRANSFER TAILGATE FITTINGS	\$	150.00	60	
13	TO TRANSFER REAR FENDER GLASSES	\$	200.00	60	
14	TO REMOVE EXHAUST PIPE	\$	150.00	80	
15	TO TRANSFER REAR LH & RH DOOR FITTINGS	\$	300.00	X	
16	TO REMOVE HYBRID BATTERY	\$	300.00	150 X	
17	TO PERFORM REPROGRAMMING OF HYBRID BATTERY	\$	380.00	150 X	

TOTAL: \$ 9,750.00

4290.

ESTIMATE REPORT

TOTAL PARTS COST: \$ 29,792.56

TOTAL LABOUR COST: \$ 9,750.00

TOTAL REPAIR COST: \$ 39,542.56

total: 17421.07
w/s: 13.9K

APPROVED DETAILS

SURVEYOR:

15 Days

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

13.9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: