

FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : NTUC22-041022/PRS/GS/ADJ/GS/cg

Your Reference: MT/1169124-001

Date : 30-May-2022

Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention : Ms Rajeswary

Dear Sir/Mdm,

SURVEY OF VEHICLE NO. FBS 4950H

Pursuant to your instruction on **23-May-2022**.

We recommend a repair cost of **\$4,150.00** (see report) based on lump sum repair and the estimated duration of repairs would take **06 days**.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Gary Soon
Automobile Appraiser

(Email : gary@fta.com.sg)

Encl. Survey Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : NTUC22-041022/PRS/GS/ADJ/GS/cg

Your Reference: MT/1169124-001

Date : 30-May-2022

Attention : Ms Rajeswary

TO : Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Assessment of Vehicle No : **FBS 4950H**
Date of Accident : **16-April-2022**
Date of Inspection : **20-April-2022**
Address of Inspection : **1 Kaki Bukit Ave 6 #02-58 S'417883**

We have carried out a physical assessment of **FBS 4950H** at **M/S H L Cycle Pte Ltd** according to your instructions on **20-Apr-2022**, dismantled items on **22-Apr-2022**, post repair survey on **29-Apr-2022** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : FBS 4950H
Make & Model : Yamaha MT-15
Year of Registration : 2021
Engine Capacity : 155 cc
Chassis No. : MH3RG711000001146
Engine No. : G3R1E0002347
Colour : Silver
Mileage (km) : 3305

2. VEHICLE CONDITION

Body Paint : Good
Steering : Serviceable
Foot Brake : Serviceable
Parking Brake : Nil

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : IRC 110/70 R17 - 70%
LH Make/Size :

Rear

RH Make/Size : IRC 140/70 R17 - 70%
LH Make/Size :

Note : % denotes the remaining percentage of the tyre


FormTeam Consultancy Pte Ltd

Our Reference : NTUC22-041022/PRS/GS/ADJ/GS/cg
Your Reference : MT/1169124-001
Vehicle Number : FBS 4950H

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **N/S & O/S** portion. Please see attached scheduled for details.



5. REMARKS

Market Value : -
Salvage Value : -
Repair Limit (Nett Loss) : -
Repairer's estimate : **Not Provided**
Nett Saving : -
Excess : -
Sum Insured : -
Our adjusted amount : **\$ 4,150.00**
Estimated Repair Days : **06 days**

Additional photographs will be submitted upon request by our principal.

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FormTeam Consultancy Pte Ltd** for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : NTUC22-041022/PRS/GS/ADJ/GS/cg

Page No. 3

Your Reference : MT/1169124-001

Vehicle Number : FBS 4950H

[illegible]

FormTeam Consultancy Pte Ltd

Our Reference : NTUC22-041022/PRS/GS/ADJ/GS/cg
 Your Reference : MT/1169124-001
 Vehicle Number : FBS 4950H

Page No. 4

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>SPECIAL NETT ITEMS</u>			
1	Rear Number Plate	Necessary	-	15.00
2	Fork Oils	Necessary	-	40.00
2	Fork Oil Seals	Necessary	-	70.00
1	Steering Cone (Set)	Necessary	-	80.00
1	Rear Tyre (Depreciation)	Cut	-	150.00
1	Rear Camera	Malfunction	-	280.00
		Special Nett Total :	-	635.00
		Parts Total :	-	4,917.20

FormTeam Consultancy Pte Ltd

Our Reference : NTUC22-041022/PRS/GS/ADJ/GS/cg
Your Reference : MT/1169124-001
Vehicle Number : FBS 4950H

Page No. 5

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	To provide towing service. (LOD)	-	-
2	To check electrical system, wire harness and focus headlamp.	-	-
3	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	-	300.00
	Labour Total :	-	300.00
	TOTAL (PARTS & LABOUR) :	-	5,217.20

The final adjusted Lump Sum contract amount is **\$ 4,150.00**
(SINGAPORE DOLLARS FOUR THOUSAND ONE HUNDRED AND FIFTY ONLY)



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser



Gary Soon
Automobile Appraiser