



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
JUSEQUITY LAW CORPORATION 133 NEW BRIDGE ROAD #10-03 CHINATOWN POINT SINGAPORE 059413		Ref: CS/LAW23003422/Uvy3e2 Date: 27/04/2023 Code: L053	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SLD 7532Y	Veh. Inspected	FBS 4950H
Policy No.		Coverage (\$)	0.00
Claim No.	JEQ/220241/0422/HC/PD/PI/kv	Excess (\$)	0.00
Assign From	KIRAN KAUR	Assign Date	24/03/2023
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA MTN 155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MH3RG711000001146	Colour	WHITE
Odometer	4833 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/70 R17	IRC	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R17	IRC	7 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE MOTORCYCLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	16/04/2022	Inspection Date	06/04/2023
Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	