

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3548B

DATE: 26.03.23

MAKE HYUNDAI

MVA JUMANI

MODEL I40

DOA: 26.03.23

CHINA

Qty	R	Type	Unit Price	Amount	
1	REAR BUMPER ASSY			dt \$553.00	
1	REAR BUMPER UNDER COVER			? \$228.00	
10	REAR BUMPER CLIPS			ney \$22.00	
1	REAR BUMPER BEAM			? \$428.40	
1	REAR BUMPER SPONGE			? \$119.50	
SUB TOTAL				\$1,350.90	
LESS 20%				\$270.18	
DISCOUNTED TOTAL				\$1,080.72	
REVERSE SENSOR				hny \$135.70	NET
REAR BUMPER MAT				hny \$50.00	NET
				\$185.70	
Labour Charge					
PANEL BEATING				280 \$300.00	
SPRAY PAINT				250 \$300.00	
REMOVE / REFIX REVERSE SENOR				30 \$50.00	
TOTAL LABOUR				\$650.00	
ESTIMATE TOTAL				\$1,916.42	
Tanjong 92495744 in p, 27/3/23 23pm LIS rising after repair Tanjong c Hyundai 2 days					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. LKK Auto Consultants hence notify the Repairer of the survey • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature Date					

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5890898

JC No 305549695

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

DUNT CARD NO.


REGN NO SHD3548B	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 27.03.2023 08:50
YR OF MANU 29.09.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093673	COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 26.03.2023
ATURE: 3P.26.03.23

/NO LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHD3548B

JU CHINA

Vehicle No.:

SHD3548B

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard