

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

31 MAR 2023

ESTIMATE

Estimate No. : b1 65495
Date Estimated : 31/03/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Bannak Mudiyansele Sandun Champik
16 Tanah Merah Kechil Link
#14-33

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 465424

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND6997Y	WBA12AK0907K41268	20/01/2022	218i Gran Coupe	7804

DESCRIPTION

To remove and replace left wing mirror.

To check electrical wiring

To respray left wing mirror cap

DESCRIPTION	VALUE
To remove and replace left wing mirror.	425 480.00
To check electrical wiring	168 177.00
To respray left wing mirror cap	70 74.00

Total Labour 1: 701.00

DESCRIPTION

LH OUTSIDE MIRROR HEATED WITH MEMOR
LH MIRROR GLASS HEATED WIDE ANDLE
LH OUTSIDE MIRROR COVER CAP PRIMED

QTY	PRIC	VALUE
1	859.90	859.90
1	435.90	435.90
1	133.90	133.90

Total Parts : 1,429.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date&Time 03/04/23 @1220 Excess S\$

Surveyor's Name PML Sign

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommended 1 day

Labour 1 701.00

Parts : 1,429.70

Labour 2 : 0.00

Excess : 0.00

Total GST @ 8% : 170.46

Grand Total : 2,301.16

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors

BMW Dealer



Final Report

Estimate No. : b1 65495
Date Estimated : 31/03/2023
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -

Bannak Mudiyansele Sandun Champik
16 Tanah Merah Kechil Link
#14-33

Singapore 465424

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND6997Y	WBA12AK0907K41268	20/01/2022	218i Gran Coupe	7804

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

* To replace LH wingmirror assembly include carrying out necessary repairs caused by the accident	425.00		425.00
---	--------	--	--------

To check electrical wiring system and lightings at the LH section for proper function	168.00		168.00
---	--------	--	--------

To respray LH wingmirror cover	70.00		70.00
--------------------------------	-------	--	-------

Sundries <i>in</i>	40.00		40.00 ✓
--------------------	-------	--	---------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

LH OUTSIDE MIRROR HEATED WITH MEMORY	859.90	1.00	0.00	859.90
LH MIRROR GLASS HEATED WIDE ANGLE	435.90	1.00	0.00	435.90
LH OUTSIDE MIRROR COVER CAP PRIMED	133.90	1.00	0.00	133.90

SUPPLEMENTARY ITEMS

Total Labour :	703.00
Total Parts :	1,429.70
Total Labour & Parts (before GST) :	2,132.70
Deduction for Excess :	
Total Repair Costs less Excess:	2,132.70
GST @8%:	170.62
Grand Total :	2,303.32

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

A Sime Darby Motors Company