

Performance Motors

BMW Dealer



Final Report

Estimate No. : b1 65495
Date Estimated : 31/03/2023
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -

Bannak Mudiyanseilage Sandun Champik
16 Tanah Merah Kechil Link
#14-33

Singapore 465424

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SND6997Y	WBA12AK0907K41268	20/01/2022	218i Gran Coupe	7804

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

* To replace LH wingmirror assembly include carrying out necessary repairs caused by the accident	425.00		425.00
---	--------	--	--------

To check electrical wiring system and lightings at the LH section for proper function	168.00		168.00
---	--------	--	--------

To respray LH wingmirror cover	70.00		70.00
--------------------------------	-------	--	-------

Sundries <i>an</i>	40.00		40.00 ✓
--------------------	-------	--	---------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

LH OUTSIDE MIRROR HEATED WITH MEMORY	859.90	1.00	0.00	859.90
LH MIRROR GLASS HEATED WIDE ANGLE	435.90	1.00	0.00	435.90
LH OUTSIDE MIRROR COVER CAP PRIMED	133.90	1.00	0.00	133.90

SUPPLEMENTARY ITEMS

Total Labour :	703.00
Total Parts :	1,429.70
Total Labour & Parts (before GST) :	2,132.70
Deduction for Excess :	
Total Repair Costs less Excess:	2,132.70
GST @8%:	170.62
Grand Total :	2,303.32

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

A Sime Darby Motors Company