

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2303-222

DATE : 31-Mar-2023

POLICY NO. : MSIG B 300613924 QMY

VEHICLE REG. NO. : SLH1678D

VEHICLE MAKE : HONDA CIVIC 1.5 TURBO CVT

TO Motor Claim Department
Allianz Global Corporate & Specialty SE
12 Marina View, Asia Square Tower 2
Singapore 018961
Tel: 6297 2529

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper	1	\$ 700.00	\$ 700.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 40.00	\$ 40.00
4	Rear Bumper Retainer LH	1	\$ 40.00	\$ 40.00
5	Rear Reinforcement	1	\$ 400.00	\$ 400.00
6	Rear Bumper Cover RH	1	\$ 40.00	\$ 40.00
7	Rear Bumper Cover LH	1	\$ 40.00	\$ 40.00
8	End Panel	1	\$ 440.00	\$ 440.00
9	End Panel Top Garnish	1	\$ 80.00	\$ 80.00
Total Spare Parts				\$ 1,830.00
SPECIAL NETT				
10	Rear License Plate with Frame	1	\$ 35.00	\$ 35.00
11	Rear Bumper Spoiler	1	\$ 180.00	\$ 180.00
12	Reverse Sensor	1	\$ 250.00	\$ 250.00
Total Special Nett				\$ 465.00
LABOUR				
13	Spray painting Rear Bumper Including Blending	1	\$ 300.00	\$ 300.00
14	Remove, Replace, Repair and Refit Affected Area	1	\$ 300.00	\$ 300.00
15	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 100.00	\$ 100.00
16	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
17	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 830.00
Amount Before Excess				\$ 3,125.00
Add GST @ 7%				218.75
Total Amount Payable				\$ 3,343.75

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

200
200
XNN
XNN
XNN
430
1160
81.2
1241.2

03 days 12104123 1128hrs
Akid 8700 5631

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary damage can be resurveyed and is subject to main/primary/first insurer's Company

Acknowledged by Repairer
Signature: