

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

**Estimate**

ESTIMATE NO. : EST2303-222

DATE : 31-Mar-2023

POLICY NO. : MSIG B 300613924 QMY

VEHICLE REG. NO. : SLH1678D

VEHICLE MAKE : HONDA CIVIC 1.5 TURBO CVT

TO Motor Claim Department  
Allianz Global Corporate & Specialty SE  
12 Marina View, Asia Square Tower 2  
Singapore 018961  
Tel: 6297 2529

FOR SURVEYOR

**ESTIMATE REPAIR COST**

| NO.                       | DESCRIPTION                                     | QUANTITY | UNIT COST | TOTAL COST         |
|---------------------------|-------------------------------------------------|----------|-----------|--------------------|
| <b>SPARE PARTS</b>        |                                                 |          |           |                    |
| 1                         | Rear Bumper                                     | 1        | \$ 700.00 | \$ 700.00          |
| 2                         | Rear Bumper Clips                               | 10       | \$ 5.00   | \$ 50.00           |
| 3                         | Rear Bumper Retainer RH                         | 1        | \$ 40.00  | \$ 40.00           |
| 4                         | Rear Bumper Retainer LH                         | 1        | \$ 40.00  | \$ 40.00           |
| 5                         | Rear Reinforcement                              | 1        | \$ 400.00 | \$ 400.00          |
| 6                         | Rear Bumper Cover RH                            | 1        | \$ 40.00  | \$ 40.00           |
| 7                         | Rear Bumper Cover LH                            | 1        | \$ 40.00  | \$ 40.00           |
| 8                         | End Panel                                       | 1        | \$ 440.00 | \$ 440.00          |
| 9                         | End Panel Top Garnish                           | 1        | \$ 80.00  | \$ 80.00           |
| <b>Total Spare Parts</b>  |                                                 |          |           | <b>\$ 1,830.00</b> |
| <b>SPECIAL NETT</b>       |                                                 |          |           |                    |
| 10                        | Rear License Plate with Frame                   | 1        | \$ 35.00  | \$ 35.00           |
| 11                        | Rear Bumper Spoiler                             | 1        | \$ 180.00 | \$ 180.00          |
| 12                        | Reverse Sensor                                  | 1        | \$ 250.00 | \$ 250.00          |
| <b>Total Special Nett</b> |                                                 |          |           | <b>\$ 465.00</b>   |
| <b>LABOUR</b>             |                                                 |          |           |                    |
| 13                        | Spray painting Rear Bumper including Blending   | 1        | \$ 300.00 | \$ 300.00          |
| 14                        | Remove, Replace, Repair and Refit Affected Area | 1        | \$ 300.00 | \$ 300.00          |
| 15                        | Remove and Refit Rear Bumper Reverse Sensor     | 1        | \$ 100.00 | \$ 100.00          |
| 16                        | Apply Rust Proofing on Replaced/Repaired Panel  | 1        | \$ 100.00 | \$ 100.00          |
| 17                        | Check and Rectify Electrical Wiring             | 1        | \$ 30.00  | \$ 30.00           |
| <b>Total Labour</b>       |                                                 |          |           | <b>\$ 830.00</b>   |

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

|                             |             |
|-----------------------------|-------------|
| <b>Total Labour</b>         | \$ 830.00   |
| <b>Amount Before Excess</b> | \$ 3,125.00 |
| <b>Add GST @ 7%</b>         | 218.75      |
| <b>Total Amount Payable</b> | \$ 3,343.75 |

03 days 12104123 1123hrs  
Akid 8700 5631

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal and financial fraud allowed
- Supplemental claim may be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: