

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Romeo Jonnalyn Alaan

Date: 04 Apr 2023

Preliminary Advice

Vehicle No	: SBM7333B	Accident Date	: 30/03/2023
Make	: NISSAN SYLPHY	Policy No.	: MP307949
Assignment Date	: 03/04/2023	Excess	: S\$250.00
Date of Inspection	: 04/04/2023	Est. Duration of Repair	: 6 days
Inspection At	: CHENG HOE MOTOR PLE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,304.70
Revised Amount	:S\$	5,354.95
Check Items (Estimated)	:S\$	342.50
Total	:S\$	5,697.45

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	32,386.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,614.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Lump Sum Basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.