

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|-------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|-----------------|-----------------------|--|
| | MS FIRST CAPITA | L INSURANCE LTD | Ref: | CS/FCI23003449/Aqy3e2 | |
| | 16 RAFFLES QUA #42-01 HONG LEC SINGAPORE 0485 | NG BUILDING | Date: | 11/04/2023 | |
| | | | Code: | FCI2 | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBA 6236T | Veh. Inspected | SML 8547U | |
| | Policy No. | D21097582 | Coverage (\$) | 0.00 | |
| | Claim No. | D23001135MFCV | Excess (\$) | 0.00 | |
| | Assign From | JOANNE TAN | Assign Date | 03/04/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA VEZEL | c.c | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | 2019 | |
| | Chassis No. | RU11314046 | Colour | PURPLE | |
| | Odometer | 73184 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 215/60 R16 | BRIDGESTONE | 6 mm | |
| | L/H Front Tyre | 215/60 R16 | BRIDGESTONE | 6 mm | |
| | R/H Rear Tyre | 215/60 R16 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 215/60 R16 | BRIDGESTONE | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 31/03/2023 | Inspection Date | 03/04/2023 | |
| | Survey held at | RYDER AUTO PTE LTD | | | |
| | | 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | |
| 5a. | Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | | |