

Vehicle Number: FBC8776C
 Model: YAMAHA SPARK
 Chassis Number: 5YP300139
 D.O.A: 29/03/2023

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey next day after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary cost must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

TP 1st Cap.
 Xiao Chen

QUANTITY	DESCRIPTION	Amount
01PCS	FRONT FENDER <i>Cracked</i>	\$ 260.00 <i>125</i>
01PCS	CLUTCH RIVER <i>cut</i>	\$ 100.00 <i>45</i>
01PCS	HANDLE GRIP (L) <i>New</i>	\$ 100.00 <i>x</i>
01PCS	SIDE COVER (R) <i>Cracked</i>	\$ 250.00 <i>170</i>
01PCS	SIDE COVER (L) <i>Cracked</i>	\$ 250.00 <i>170</i>
01PCS	INNER FARING <i>Cracked</i>	\$ 160.00 <i>120</i>
01PCS	SIDE CENTRA COVER (L) <i>Cracked</i>	\$ 140.00 <i>120</i>
01PCS	REAR SIDE FARING (L) <i>Cracked</i>	\$ 280.00 <i>200</i>
01PCS	REAR SIDE FARING (R) <i>New</i>	\$ 280.00 <i>x</i>
01PCS	HEAD LAMP COWLING <i>Cracked</i>	\$ 250.00 <i>180</i>
01PCS	FRONT SIGNAL LAMP (L) <i>Cracked</i>	\$ 210.00 <i>120</i>
01PCS	FRONT SIGNAL LAMP (R) <i>New</i>	\$ 210.00 <i>x</i>
01PCS	FRONT SIGNAL LAMP FARING <i>Cracked</i>	\$ 260.00 <i>200</i>
01PCS	BATTERY BOX <i>New</i>	\$ 180.00 <i>x</i>
01PCS	FRONT FOOTREST ARM <i>New</i>	\$ 220.00 <i>x</i>
01PCS	REAR FOOTREST ARM (L) <i>New</i>	\$ 140.00 <i>50</i>
01PCS	REAR FOOTREST ARM (R) <i>New</i>	\$ 140.00 <i>50</i>
01PCS	BRAKE PADEL <i>New</i>	\$ 180.00 <i>x</i>
01PCS	GEAR RIVER <i>New</i>	\$ 145.00 <i>x</i>
01PCS	SIDE STAND <i>New</i>	\$ 145.00 <i>x</i>
01PCS	FRONT BASKET <i>New</i>	\$ 140.00 <i>x</i>
01PCS	KEY SWITCH COVER (CARBON) <i>cut</i>	\$ 320.00 <i>250</i>
01PCS	AIR FILTER TOP COVER (CARBON) <i>New</i>	\$ 220.00 <i>x</i>
01PCS	METRA INNER COVER <i>New</i>	\$ 205.00 <i>x</i>
01PCS	HANDLE BAR <i>New</i>	\$ 230.00 <i>x</i>
01PCS	FRONT FORK SET <i>New</i>	\$ 450.00 <i>x</i>
01PCS	REAR BOX <i>cut</i>	\$ 600.00 <i>200 (SN)</i>
01PCS	REAR BOX BRACKET <i>New</i>	\$ 240.00 <i>x</i>
01PCS	SEAT CUSION <i>New</i>	\$ 300.00 <i>x</i>
01PCS	EXHAUST <i>New</i>	\$ 1,800.00 <i>x</i>
Total:		\$ 8,185.00

SPECIAL NETT

01PCS	BODY STICKER <i>New</i>	\$ 200.00 <i>150</i>
Total:		\$ 200.00

LABOUR

- To supply labour & parts to replace above mentioned parts : *580*
- To supply labour & paint to spray accident affected Area :
- To supply labour for repair wiring electric part :
- To supply labour for repair rear box bracket broken bolt :

Total Labour: \$ 1,600.00

Total Parts \$8,185.00+Special Nett \$200.00+Total Labour \$1,600.00 = \$ 9,985.00

2.214

total: ~~2740~~
 2750
 H/S: P.22K

Adrian
 1/5 03/04/23
 OK Pmp