

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 03.04.2023

Xiao Chen

TO : **SOMPO** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SFK3836G**  
MODEL : **HONDA CIVIC**  
DATE OF ACCIDENT : 01.04.2023  
TIME OF ACCIDENT : 14:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                   | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-----------------------------------------------|-----|-----------------|------------------|
| 1   | BOOTLID <i>Dented</i>                         | 1   | \$ 610.70       | \$ 610.70        |
| 2   | BOOTLID REFLECTOR <i>LH at, RH Cracked</i>    | 2   | \$ 179.90       | \$ 359.80        |
| 3   | BOOTLID KEY LOCK <i>new</i>                   | 1   | \$ 198.40       | \$ 198.40        |
| 4   | BOOTLID NUMBER PLATE LAMP <i>new</i>          | 2   | \$ 37.80        | \$ 75.60         |
| 5   | BOOTLID NUMBER PLATE COVER GARNISH <i>new</i> | 1   | \$ 171.60       | \$ 171.60        |
| 6   | BOOTLID INNER STOPPER <i>new</i>              | 2   | \$ 18.00        | \$ 36.00         |
| 7   | BOOTLID HINGE <i>new</i>                      | 2   | \$ 78.00        | \$ 156.00        |
| 8   | BOOTLID INSULATOR <i>new</i>                  | 1   | \$ 210.70       | \$ 210.70        |
| 9   | BOOTLID TOP LOCK <i>Damaged</i>               | 1   | \$ 194.50       | \$ 194.50        |
| 10  | BOOTLID LOWER LOCK <i>new</i>                 | 1   | \$ 15.00        | \$ 15.00         |
| 11  | BOOTLID LOGO <i>2</i>                         | 1   | \$ 35.70        | \$ 35.70         |
| 12  | BOOTLID EMBLEM '2.0' <i>new</i>               | 1   | \$ 28.00        | \$ 28.00         |
| 13  | BOOTLID EMBLEM 'V-TECH'                       | 1   | \$ 37.10        | \$ 37.10         |
| 14  | BOOTLID EMBLEM 'CIVIC'                        | 1   | \$ 29.10        | \$ 29.10         |
| 15  | BOOTLID WEATHER STRIP <i>cut</i>              | 1   | \$ 169.70       | \$ 169.70        |
| 16  | REAR FENDER COWLING <i>new</i>                | 2   | \$ 79.80        | \$ 159.60        |
| 17  | REAR FENDER INNER TRIM <i>LH Dented</i>       | 2   | \$ 298.80       | \$ 597.60        |
| 18  | REAR FENDER AIR VENT LH <i>new</i>            | 1   | \$ 72.60        | \$ 72.60         |
| 19  | REAR BUMPER <i>Dented</i>                     | 1   | \$ 698.60       | \$ 698.60        |
| 20  | REAR BUMPER SIDE RETAINER <i>new</i>          | 2   | \$ 24.10        | \$ 48.20         |
| 21  | REAR BUMPER EXHAUST GARNISH <i>new</i>        | 1   | \$ 59.90        | \$ 59.90         |

298.80



TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SFK3836G**  
 MODEL : **HONDA CIVIC**  
 DATE OF ACCIDENT : 01.04.2023  
 TIME OF ACCIDENT : 14:50 HOURS

|    |                                          |   |           |           |   |
|----|------------------------------------------|---|-----------|-----------|---|
| 22 | REAR BUMPER BRACKET <i>New</i>           | 2 | \$ 28.80  | \$ 57.60  | + |
| 23 | TAILLAMP <i>LH ut, RH cnd</i>            | 2 | \$ 299.40 | \$ 598.80 | — |
| 24 | TAILLAMP PANEL <i>Reps</i>               | 2 | \$ 198.20 | \$ 396.40 | + |
| 25 | TAILLAMP LOWER BRACKET <i>New</i>        | 2 | \$ 29.10  | \$ 58.20  | + |
| 26 | REAR END PANEL <i>Dented</i>             | 1 | \$ 360.00 | \$ 360.00 | — |
| 27 | REAR END PANEL TOP GARNISH <i>Dented</i> | 1 | \$ 114.40 | \$ 114.40 | — |
| 28 | REAR FLOOR PANEL <i>Buckled</i>          | 1 | \$ 992.20 | \$ 992.20 | — |
| 29 | REAR FLOOR PANEL TOP BOARD <i>Dented</i> | 1 | \$ 316.00 | \$ 316.00 | — |
| 30 | REAR SPARE TYRE BOLT <i>New</i>          | 1 | \$ 29.20  | \$ 29.20  | + |
| 31 | REAR TOOLS SPONGE TRAY <i>Cnd</i>        | 1 | \$ 104.50 | \$ 104.50 | — |
| 32 | REAR CHASSIS MEMBER <i>Reps</i>          | 1 | \$ 968.90 | \$ 968.90 | + |
| 33 | CENTER EXHAUST                           | 1 | \$ 870.90 | \$ 870.90 | + |
| 34 | CENTER EXHAUST INSULATOR                 | 1 | \$ 136.40 | \$ 136.40 | + |
| 35 | REAR EXHAUST PIPE <i>MP</i>              | 1 | \$ 745.40 | \$ 745.40 | + |
| 36 | REAR EXHAUST INSULATOR <i>MP</i>         | 1 | \$ 143.80 | \$ 143.80 | + |
| 37 | REAR EXHAUST MOUNTING                    | 2 | \$ 16.00  | \$ 32.00  | + |
| 38 | REAR EXHAUST GASKET (SET)                | 1 | \$ 16.00  | \$ 16.00  | + |

4996.10

3996.88

TOTAL PRICE \$ 9,905.10  
 LESS 20% \$ 1,981.02  
 SUB TOTAL PRICE \$ 7,924.08

| S/N | DESCRIPTION                                             | QTY | UNIT S/NETT | TOTAL S/NETT |     |
|-----|---------------------------------------------------------|-----|-------------|--------------|-----|
| 1   | REAR NUMBER PLATE <i>New</i>                            | 1   | \$ 50.00    | \$ 50.00     | +   |
| 2   | REAR BUMPER CLIP (SET) <i>New</i>                       | 1   | \$ 50.00    | \$ 50.00     | 50  |
| 3   | REAR BUMPER LOWER SPOILER (SPECAIL TYPE) <i>Dented</i>  | 1   | \$ 1,800.00 | \$ 1,800.00  | 850 |
| 4   | TAIL LAMP CLIP <i>New</i>                               | 4   | \$ 30.00    | \$ 120.00    | 20  |
| 5   | TAILLAMP PANEL SEALANT <i>xtc New</i>                   | 2   | \$ 60.00    | \$ 120.00    | X   |
| 6   | BOOTLID SEALANT <i>New</i>                              | 1   | \$ 60.00    | \$ 60.00     | 40  |
| 7   | BOOTLID NUMBER PLATE COVER GARNISH CLIP (SET) <i>MP</i> | 1   | \$ 20.00    | \$ 20.00     | +   |
| 8   | REAR FENDER COWLING CLIP (SET) <i>New</i>               | 1   | \$ 60.00    | \$ 60.00     | +   |
| 9   | REAR FENDER INNER TRIM CLIPS (SET) <i>New</i>           | 1   | \$ 60.00    | \$ 60.00     | 30. |
| 10  | REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>       | 1   | \$ 50.00    | \$ 50.00     | 20  |
| 11  | REAR END PANEL INSULATION SEAL <i>New</i>               | 1   | \$ 120.00   | \$ 120.00    | 60. |
| 12  | REAR FLOOR PANEL INSULATION SEAL <i>New</i>             | 1   | \$ 350.00   | \$ 350.00    | 20  |



TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SFK3836G**  
 MODEL : **HONDA CIVIC**  
 DATE OF ACCIDENT : 01.04.2023  
 TIME OF ACCIDENT : 14:50 HOURS

|    |                                       |   |           |                                 |
|----|---------------------------------------|---|-----------|---------------------------------|
| 13 | TRIANGLE BREAKDOWN SIGN <i>Delint</i> | 1 | \$ 180.00 | \$ <del>180.00</del> <i>60</i>  |
| 14 | REAR EXHAUST CHROME PIPE <i>New</i>   | 2 | \$ 250.00 | \$ 500.00 <i>x</i>              |
| 15 | REVERSE SENSOR <i>Damaged</i>         | 1 | \$ 220.00 | \$ <del>220.00</del> <i>200</i> |

*1510* TOTAL \$ 3,760.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING**

| S/N | JOB DESCRIPTION                                                                               | PRICE                  | ADJUSTED COST |
|-----|-----------------------------------------------------------------------------------------------|------------------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                                    | \$ <del>2,200.00</del> | <i>1200</i>   |
| 2   | TO SPRAY PAINT AFFECTED AREA                                                                  | \$ <del>1,600.00</del> | <i>900</i>    |
| 3   | TUFF COAT                                                                                     | \$ <del>250.00</del>   | <i>80</i>     |
| 4   | WIRING CHECK                                                                                  | \$ <del>250.00</del>   | <i>30</i>     |
| 5   | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR                | \$ <del>180.00</del>   | <i>80</i>     |
| 6   | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                          | \$ <del>80.00</del>    | <i>50</i>     |
| 7   | REAR CHASSIS ALIGNMENT                                                                        | \$ 250.00              | <i>x</i>      |
| 8   | TRANFER BOOTLID MECHANISM                                                                     | \$ <del>80.00</del>    | <i>60</i>     |
| 12  | CONDUCT WATER LEAKAGE TEST                                                                    | \$ 80.00               | <i>x</i>      |
| 13  | REMOVE AND REFIX REAR EXHAUST PIPE                                                            | \$ 180.00              | <i>x</i>      |
| 14  | REMOVE AND REFIX REAR BUMPER LOWER SPOILER                                                    | \$ 200.00              | <i>x</i>      |
| 16  | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00              | <i>x</i>      |

TOTAL \$ 5,530.00 *2400*

TO : **SOMPO** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SFK3836G**  
MODEL : **HONDA CIVIC**  
DATE OF ACCIDENT : 01.04.2023  
TIME OF ACCIDENT : 14:50 HOURS

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 11,684.08  
TOTAL LABOUR COST : \$ 5,530.00  
TOTAL REPAIR COST : \$ 17,214.08

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

Adrian G  
h/s 03/04/23.

09 Days

total: 7806.88  
h/s: 610 (Nett Value)  
✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: