

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 03.04.2023
 VEH NO : SLC5052J
 MODEL : Mazda 3
 D O A : 01.04.2023
 YR REF : SLR7285L

Ezlyna

JM6BM42A8G0338404

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC5052J (MAZDA 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Repair</i>	1	1,143.50 <i>x</i>
2	Rear Bumper Side Holder <i>new</i>	1	38.20 <i>x</i>
3	Rear Fender - LH <i>Repair</i>	1	1,025.80 <i>x</i>
4	Rear Windscreen Moulding <i>new</i>	1	105.40 <i>x</i>
5	Rear Door - LH <i>Dented</i>	1	1,049.40 <i>✓</i>
6	Rear Door Lock - LH <i>new</i>	1	284.80 <i>x</i>
7	Rear Door Weatherstripe - LH <i>new</i>	1	182.40 <i>x</i>
8	Rear Door Inner Trimboard - LH <i>Dented</i>	1	698.40 <i>✓</i>
9	Rear Door Glass Regulator Gear - LH <i>new</i>	1	368.90 <i>✓</i>
10	Rear Door Glass Regulator Motor - LH <i>new</i>	1	395.60 <i>x</i>
11	Front Door - LH <i>Dented</i>	1	1,098.80 <i>✓</i>
12	Front Door Lock - LH <i>new</i>	1	269.50 <i>✓</i>
13	Front Door Weatherstripe - LH <i>new</i>	1	199.50 <i>x</i>
14	Front Door Inner Trimboard - LH <i>Dented</i>	1	673.50 <i>✓</i>
15	Front Door Glass Regulator Gear - LH <i>new</i>	1	379.10 <i>✓</i>
16	Front Door Glass Regulator Motor - LH <i>new</i>	1	390.50 <i>x</i>
17	Front Door Outer Handle - LH <i>new</i>	1	224.20 <i>x</i>
18	Rear Lower Arm <i>Best</i>	1	398.70 <i>✓</i>
19	Rear Trailing Arm <i>Best</i>	1	494.90 <i>✓</i>
20	Rear Knuckle Arm <i>new</i>	1	498.40 <i>✓</i>
21	Rear Stay Arm <i>Best</i>	1	184.20 <i>✓</i>
22	Rear Wheel Hub c/w Bearing <i>new</i>	1	349.70 <i>✓</i>
23	Rear Shock Absorber <i>Best</i>	1	389.70 <i>✓</i>
24	Rear Anti Roll Bar Linkage <i>Best</i>	1	101.80 <i>✓</i>
25	Rocker Panel - LH <i>Dented</i>	1	10,944.90
	Less 20%		(2,188.98)
			\$ 8,755.92

7720.50

6176.40

265.50

S/NETT ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SLC5052J (MAZDA 3)

1	Rear Bumper Clips	\$	30.00	X
2	Rear Windscreen Sealant	\$	60.00	X
3	Rear Door Inner Trimboard Clips - LH	\$	30.00	✓
4	Rear Door Black Tape - LH	\$	60.00	✓
5	Front Door Inner Trimboard Clips - LH	\$	30.00	✓
6	Front Door Black Tape - LH	\$	60.00	✓
7	Rear Wheel Rim - LH	\$	880.00	650.
8	Rear Tyre - LH	\$	250.00	X

Total Parts

\$ 10,155.92

LABOUR CHARGE

1	To knocking & pull out front left & rear portion & renew above parts	\$	1,400.00	1000
2	To putty & spray up paint works	\$	1,200.00	1000
3	To check wiring	\$	50.00	30
4	To apply tuff coat	\$	150.00	80
5	To remove reverse sensor	\$	100.00	50
6	To remove upholstery	\$	150.00	30
7	To remove rear windscreen	\$	180.00	X
8	To transfer front and rear door fittings	\$	300.00	160
9	To dismantle rear undercarriage	\$	350.00	220
10	To perform wheel alignment	\$	150.00	80

Total Labour

\$ 4,030.00

Grand Total

\$ 14,185.92

NOTE : -

LKK Auto Company PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices agreed with LKK Auto Company
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9656.40
H/S: 7.7K.
10 Days.