

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AIG	DATE	: 3-Apr-23
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SNF7774G		
MODEL	: TOYOTA NOAH		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
	DATE	: 2-Apr-23	
	TIME	: 0910HRS	
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR <i>Ne m</i>	1	\$ 1,655.30	\$ 1,655.30
2	FRONT SIDE SKIRT <i>Rg</i>	1	\$ 860.00	\$ 860.00
3	FRONT BONNET <i>Dented</i>	1	\$ 930.20	\$ 930.20
4	FRONT BONNET HINGE <i>new</i>	2	\$ 90.00	\$ 180.00
5	FRONT BONNET LOCK <i>Ne m</i>	1	\$ 180.00	\$ 180.00
6	FRONT BONNET OUTER GARNISH <i>crushed</i>	1	\$ 355.30	\$ 355.30
7	FRONT BONNET BRACE PANEL <i>Best</i>	1	\$ 110.00	\$ 110.00
8	FRONT BUMPER <i>Distorted</i>	1	\$ 855.90	\$ 855.90
9	FRONT BUMPER SIDE RETAINER <i>RH Dgd</i>	2	\$ 62.40	\$ 124.80
10	FRONT BUMPER FOG LAMP COVER <i>at</i>	1	\$ 155.30	\$ 155.30
11	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 520.00	\$ 520.00
12	FRONT BUMPER REINFORCEMENT SPONGE <i>crushed</i>	1	\$ 180.00	\$ 180.00
13	FRONT BUMPER UNDER COVER <i>Ne m</i>	1	\$ 455.60	\$ 455.60
14	FRONT FENDER <i>Dented</i>	1	\$ 822.60	\$ 822.60
15	FRONT FENDER INNER COWLING <i>Tom</i>	1	\$ 280.30	\$ 280.30
16	FRONT CENTRE GRILLE TOP <i>crushed</i>	1	\$ 922.30	\$ 922.30
17	FRONT CENTRE GRILLE BOTTOM <i>Ne m</i>	1	\$ 930.50	\$ 930.50
18	FRONT GRILLE SIDE GARNISH <i>Ne m</i>	1	\$ 90.00	\$ 90.00
19	FRONT GRILLE LOGO <i>Ne m</i>	1	\$ 103.00	\$ 103.00

20	HEADLAMP HID <i>cracked</i>	2	\$ 3,855.30	\$ <u>7,710.60</u>	<i>7212</i>
21	HEADLAMP OUTER PROTECTOR <i>Ne m</i>	2	\$ 90.00	\$ 180.00	<i>t</i>
22	FRONT SUPPORT PANEL <i>Peris</i>	1	\$ 1,355.20	\$ 1,355.20	<i>t</i>
23	FRONT SHOCK ABSORBER <i>Butt</i>	1	\$ 566.20	\$ <u>566.20</u>	<i>432</i>
24	FRONT LOWER ARM <i>Butt</i>	1	\$ 455.30	\$ 455.30	<i>t</i>
25	FRONT KNUCKLE ARM <i>Butt</i>	1	\$ 520.00	\$ 520.00	<i>t</i>
26	FRONT KNUCKLE ARM BEARING <i>Butt</i>	1	\$ 510.00	\$ <u>510.00</u>	<i>331</i>

13664.30
10248.22

TOTAL PRICE \$ 21,008.40
LESS 25% \$ 5,252.10
SUB TOTAL PRICE \$ 15,756.30

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT SIDE SKIRT CLPIS(SET) <i>Ne m</i>	1	\$ 20.00	\$ 20.00
2	FRONT NUMBER PLATE <i>Ne m</i>	1	\$ 50.00	\$ 50.00
3	FRONT BONNET OUTER GARNISH CLIPS(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
4	FRONT BUMPER CLIP (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
5	FRONT FENDER INNER COWLING CLIPS(SET) <i>Ne</i>	1	\$ 22.00	\$ 22.00
6	WHEEL RIM <i>Lot</i>	1	\$ 1,200.00	\$ 1,200.00
7	WHEEL TYRE <i>Ne m</i>	1	\$ 350.00	\$ 350.00

512

TOTAL \$ 1,682.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>800</i>	
3	TUFF COAT	\$ 180.00	<i>60</i>	
4	WIRING CHECK	\$ 150.00	<i>30</i>	
5	TO REMOVE AND REFIX AIR CON CONDENSOR AND TOP UP GAS	\$ 100.00	<i>x</i>	
6	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 100.00	<i>x</i>	
7	TO REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 150.00	<i>x</i>	
8	FOUR WHEEL ALIGHMENT	\$ 120.00	<i>80</i>	

	REMOVE AND REFIX FRONT 9 UNDERCARRIAGE	\$ 350.00	2W	
--	---	-----------	----	--

TOTAL

\$4,350.00

1970

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,438.30
TOTAL LABOUR COST : \$ 4,350.00
TOTAL REPAIR COST : \$ 21,788.30

Adrian Ling
2/s 04/04/23.

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

08 days.

total: 1273022

u/s: 10-1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: