



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC Life (Singapore) Pte Ltd

DATE: 04/08/2023

Survey details

Date of loss	1/4/2023
Date of appointment	3/4/2023
Date of survey	5/4/2023
Location of survey	HIAP LEK AUTOMOBILE TRADING

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	JSK 674
Make and Model	HONDA
Date of registration	2017
Excess	
Market Value	RM 4,300.00
Parf Rebate	
Nett Loss	

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	5 days (est)

Remarks:

Damages Consistent.

The estimate repair cost of the damaged vehicle is in the region of \$4,000.00 to \$5,000.00