

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM 23003463/4993

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SND 6082L

at Workshop m/s JSSM 02-13

of \_\_\_\_\_

Insured: SNC 5628X

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8138k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: 86669655

Veh No: SND 6082L Yr Regn: 01/07/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: BMW M3 4.0A c.c 3999

Colour matte Black A/C: Insured / Std / NI / NA

Sp. Reading 101540 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBSK692010E697857

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35ZR19

R: 275/35ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front 6 mm Rear 6 mm

R/Bal. \_\_\_\_\_ mm L/Bal. 6 mm

D.O.A. 31/03/23 D.O.I. 4/4/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Pat

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>3/5/23</u>	<u>Dep 17k.</u> <u>COE under 30-04-2023 LIA #38181</u> <u>4/5 @ 4300 in hand Repair</u>

Date/Time, File Pass to?  : Preli. Report  : Final Report

Days Of Repair: \_\_\_\_\_ Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_ Date/Time, File Return to? 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

Report Format: \_\_\_\_\_ Lump Sum / I.B.I: (\$) \_\_\_\_\_

**ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS**

Vehicle No. : SND 6082 L  
 Chassis No. : WBSKG92010E697857  
 Engine No. : 21524929S65B40A  
 Date of Accident : 31.03.2023

Reference No. : 230331-TPC-JSSM03  
 Make/Model : BMW / M3  
 Date : 03.04.2023

**Replacement of Damaged Parts**

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	LH Door	Damaged	\$ 2,066.00	\$ 1,859.40
2	1	Front LH Fender	Damaged	\$ 1,303.00	\$ 1,172.70
3	1	Front LH Fender Air Vent Emblem	Damaged	\$ 283.00	\$ 254.70
4	1	LH Side Skirt	Damaged	\$ 666.00	\$ 599.40
5	1	Front Bumper	Scratched	\$ 1,888.00	\$ 1,609.20
6	1	LH Side Mirror	Scratched	\$ 906.00	\$ 815.40
7	1	Front LH Alloy Sport Rim	Dented	\$ 990.00	\$ 891.00
8	1	Front LH Michelin Tyre (255/35/ZR19)	Punctured	\$ 268.00	\$ 247.20
9	1	Front Bumper LH Bracket	Broken	\$ 165.00	\$ 148.50
<b>Total (Parts):</b>				<b>\$ 8,535.00</b>	<b>\$ 6,401.25</b>

*Handwritten notes:*  
 Body 1589.34  
 metal 1022.38  
 Scr 162.00  
 cur ✓  
 r X  
 r X  
 cur ✓  
 cur/pur 602 160 S/N  
 r X  
 102

**Labour Charges**

26	To fix & dismantle and remove damaged Front left Portions; affected damaged portion.	\$ 600.00	400
27	To apply anti rust coat and affected areas	\$ -	
28	To check wiring	\$ 180.00	60
29	Welding and cutting of affected panels, including chassis alignment.	\$ -	
30	Spray painting for Front Portions affected parts	\$ 1,000.00	800
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ 120.00	11 X
33	3D Wheel Alignment	\$ -	
34	To Apply Waterproofing sealer on Front Support Panels	\$ -	
<b>Total Labour:</b>		<b>\$ 1,900.00</b>	

**Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 8,301.25**

Less 10% **\$ 7,471.13**

*Handwritten calculations:*  
 4428.72  
 102  
 2- 3986.74  
 S.N- 160  
 L- 1160  
 5406.74  
 202  
 4325

*Handwritten notes:*  
 not authorized  
 den  
 moray  
 tel: 62563561  
 1/4 9 4300  
 Hdays  
 Take photo After repair  
 parts price checking  
 4/5 4300

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: