

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 14 Jun 2023

**Preliminary Advice**

Vehicle No	: SLF9294K	Accident Date	: 31/03/2023
Make	: MAZDA 3	Policy No.	: SP2004246356-01
Assignment Date	: 03/04/2023	Excess	: S\$600.00
Date of Inspection	: 04/04/2023	Est. Duration of Repair	: 4
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (Desktop Survey)		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,688.00
Revised Amount	:S\$	6,781.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,781.00
 Lump Sum Repair	 :S\$	 4,750.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	27,193.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,807.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Kindly approve on cost the of repair. Lump Sum Basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.