

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Registration No

Owner's Name

Ins Policy No. Date of Accident

Chassis No

Model

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT23000988

Page

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07

: CIVIC 1.5 TURBO VTIS YM2016

THE CONCOURSE SINGAPORE 199555

: MRHFC1660GT000464

: CHAY JUNFENG

Customer No. Svc Advisor

: 1. Apr 2023

Date

: WZL009

Engine No

: ANIKKA LAI SWEE KAM

: L15B71629356

Date | Time

: 1. Apr 2023 12:03:31 PM

Surveyor Name

Survey Date

Unit Price Disc %

Authorisation Date

: 30/3/2023

: SLL1916X

8% GST Amount Amount

Amount incld GST

Description Item TP DIRECT SETTLEMENT (J/NO:

OWNER: CHAY JUNFENG

OWNER INSURER: TOKIO MARINE

ACC DATE: 30/03/2023

SURVEYED BY:

DATE:

REF NO:

TP INSURER: LONPAC

TP VEH: YM7773S

| FACEFR.BUMPER / ? | | 1 | 579.90 | 25 CM | 434.92 | 34.79 | 469.71 |
|--|---|--|---|--|--|--|---|
| | M | 1 | 10.40 | 25 | 7.80 | 0.62 | 8.42 |
| | na | 10 | 2.30 | 25 | 17.25 | 1.38 | 18.63 |
| | r | 1 | 16.50 | 25 | 12.37 | 0.99 | 13.36 🔨 |
| | wi | 1 | 85.10 | 25 | 63.82 | 5.11 | 68.93 |
| | cm | 1 | | 25 | 86.85 | 6.95 | 93.80 |
| | - | | | | 74.10 | 5.93 | 80.03 🔨 |
| | | | | | | | 14.09 |
| | | | | | | | 25.76 |
| RUBBERHOOD SEAL | nn 🔽 | 1 | | | | | |
| HEADLIGHT ASSYL. | nn 💈 | 1 | 1373.00 | 25 | 1029.75 | 82.38 | 1112.13 |
| | | | | Sum Item | 1763.76 | 141.10 | 1,904.86 |
| | | | | | | | 200 |
| SUNDRIES | | 1 | 100.00 | 201 | 100.00 | 8.00 | 108.00 |
| INSPECT FR LIGHTING MECHANISMS & FOO | CUS | 1 | 160.00 | | 160.00 | 12.80 | 172.80 |
| | | 1 | 1500.00 | 6301 | 1500.00 | 120.00 | 1620.00 |
| SPRAY PAINTING ON REPAIRED OR REPLAC (1P) | ED AREAS | S. ₁ | 1200.00 | 5201 | 1200.00 | 96.00 | 1296.00 |
| N E | | | | Sum Labor | 2960.00 | 236.80 | 3,196.80 |
| | SPACERL.FR.BUMPER SIDE CLIP,BUMPER GARNISHL.FR.BUMPER SIDE BASE,FR.GRILLE CHROME MOLDINGFR.GRILLE EXTENSION ASSYL.FR.GRILLE EMBLEM RUBBERHOOD SEAL HEADLIGHT ASSYL. SUNDRIES INSPECT FR LIGHTING MECHANISMS & FOOR REMOVE & RENEW FR BUMPER INCLUDING ON SPRAY PAINTING ON REPAIRED OR REPLACE | SPACERL.FR.BUMPER SIDE CLIP,BUMPER GARNISHL.FR.BUMPER SIDE BASE,FR.GRILLE CHROME MOLDINGFR.GRILLE EXTENSION ASSYL.FR.GRILLE EMBLEM RUBBERHOOD SEAL HEADLIGHT ASSYL. SUNDRIES INSPECT FR LIGHTING MECHANISMS & FOCUS REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON SPRAY PAINTING ON REPAIRED OR REPLACED AREAS | SPACERL.FR.BUMPER SIDE CLIP,BUMPER GARNISHL.FR.BUMPER SIDE BASE,FR.GRILLE CHROME MOLDINGFR.GRILLE EXTENSION ASSYL.FR.GRILLE EMBLEM RUBBERHOOD SEAL HEADLIGHT ASSYL. SUNDRIES INSPECT FR LIGHTING MECHANISMS & FOCUS REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. | SPACERL.FR.BUMPER SIDE 1 10.40 CLIP,BUMPER 10 2.30 GARNISHL.FR.BUMPER SIDE 1 16.50 BASE,FR.GRILLE CHROME 1 85.10 MOLDINGFR.GRILLE 1 115.80 EXTENSION ASSYL.FR.GRILLE 1 198.80 EMBLEM 1 17.40 RUBBERHOOD SEAL 1 31.80 HEADLIGHT ASSYL. 1 1373.00 SUNDRIES 1 100.00 INSPECT FR LIGHTING MECHANISMS & FOCUS 1 160.00 REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON REPAIRED OR REPLACED AREAS. 1 1500.00 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1 1200.00 | SPACERL.FR.BUMPER SIDE CLIP,BUMPER GARNISHL.FR.BUMPER SIDE BASE,FR.GRILLE CHROME MOLDINGFR.GRILLE EXTENSION ASSYL.FR.GRILLE EMBLEM RUBBERHOOD SEAL HEADLIGHT ASSYL. SUNDRIES INSPECT FR LIGHTING MECHANISMS & FOCUS REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P) 100.00 25 110.40 25 16.50 25 44 1 16.50 25 45 1 15.80 25 47 1 15.80 25 47 1 17.40 25 Sum Item 1 100.00 1 1500.00 1 1500.00 1 1500.00 1 1500.00 1 12 | SPACERL.FR.BUMPER SIDE CLIP,BUMPER GARNISHL.FR.BUMPER SIDE M. 10 2.30 25 17.25 GARNISHL.FR.BUMPER SIDE M. 10 2.30 25 12.37 BASE,FR.GRILLE CHROME MOLDINGFR.GRILLE EXTENSION ASSYL.FR.GRILLE EXTENSION ASSYL.FR.GRILLE EMBLEM RUBBERHOOD SEAL HEADLIGHT ASSYL. SUNDRIES IN 1 100.00 20 100.00 INSPECT FR LIGHTING MECHANISMS & FOCUS REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1 1200.00 520 120.00 (1P) | SPACERL.FR.BUMPER SIDE CLIP,BUMPER GARNISHL.FR.BUMPER SIDE M 1 10.40 25 7.80 0.62 CLIP,BUMPER GARNISHL.FR.BUMPER SIDE M 1 16.50 25 12.37 0.99 BASE,FR.GRILLE CHROME MOLDINGFR.GRILLE EXTENSION ASSYL.FR.GRILLE EXTENSION ASSYL.FR.GRILLE EMBLEM RUBBERHOOD SEAL HEADLIGHT ASSYL. Nn 7 1 31.80 25 23.85 1.91 HEADLIGHT ASSYL. Nn 7 1 1373.00 25 1029.75 82.38 Sum Item 1763.76 141.10 SUNDRIES INSPECT FR LIGHTING MECHANISMS & FOCUS INSPECT FR LIGHTING MECHANISMS & FOCUS REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1 1200.00 96.00 (1P) |

)

Printed on 1/4/2023 12:11:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2.00p@ementary item(s) must be resurveyed and However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07

THE CONCOURSE

SINGAPORE 199555

Registration No : SLL1916X

Chassis No : MRHFC1660GT000464

Model Owner's Name

: CIVIC 1.5 TURBO VTIS YM2016

: CHAY JUNFENG

Ins Policy No.

Date of Accident : 30/3/2023 Document No.

Date

Qty

: SQT23000988

: 1. Apr 2023

Customer No. : WZL009

Svc Advisor

: ANIKKA LAI SWEE KAM

Engine No

: L15B71629356

Date | Time

: 1. Apr 2023 12:03:31 PM

Surveyor Name

Survey Date

Authorisation Date

Unit Price Disc %

8% GST **Amount**

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

Amount incld GST

2

Page

Item Description Survey By Date & Time Excess Status Signature

Total Amount 4,723.76 Total (Inclusive of GST)

377.90 5,101.66

5,101.66

Printed on 1/4/2023 12:11:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.