



Mercedes-Benz

Finalization

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNB4393M

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT  
5 MAXWELL ROAD #17-00  
TOWER BLOCK, MND COMPLEX  
SINGAPORE 069110  
62239433

## Vehicle &amp; Document Information

WIP No 64027  
Reg No/Reg Date SNB4393M / 23/08/2021  
Date In/Mileage 10/04/2023/ 17977  
Chassis No W1N2476842W1208263  
Engine No 28291480528077  
Make/Model MB/GLB 180  
Colour/Trim 021 191 Cosmos Blac/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
WE000058	Credit	06/05/2023/ 16:54	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 7210095699-01 // 29-3-2023								
DRIVE IN/EXCESS : 31-3-2023 // SLD1801K - EQ								
DATE IN/DATE SURVEY: 10-4-2023 // TAUFIKH - LKK								
DIRECT SETTLEMENT BY: 4-4-2023 // NEO JIE SI - EQ								1440.00
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							0.05	1600.00
A BPIRES								
RESPRAY FRONT BUMPER & RH/FRONT FENDER							0.10	380.00
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								120.00
A BPILAB								
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								
X RH/FRONT COVER, FENDER & BUMPER AREA					1.00	268.90	00.00	268.90
X FRONT BUMPER					1.00	1240.82	00.00	1240.82
X LH/UPPER BASIC CARRIER FOR BUMPER					1.00	53.72	00.00	53.72
X RH/UPPER BASIC CARRIER FOR BUMPER					1.00	62.80	00.00	62.80
X FRONT BUMPER BOTTOM BLACK TRIM COVER					1.00	260.96	00.00	260.96
X RIVET FOR BUMPER					10.00	5.34	00.00	53.40
X RH/HEADLAMP UNIT					1.00	3361.30	00.00	3361.30

Confirmed &amp; accepted by

Nett 8,841.90  
8% GST on 8841.90 707.35  
Total Payable 9,549.25

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

**SUPPLEMENTARY**

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNB4393M

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT  
5 MAXWELL ROAD #17-00  
TOWER BLOCK, MND COMPLEX  
SINGAPORE 069110  
62239433

### Vehicle & Document Information

WIP No **64027**  
Reg No/Reg Date **SNB4393M / 23/08/2021**  
Date In/Mileage **10/04/2023/ 17977**  
Chassis No **W1N2476842W1208263**  
Engine No **28291480528077**  
Make/Model **MB/GLB 180**  
Colour/Trim **021 191 Cosmos Blac/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator				
WE000058	Credit	06/05/2023/ 16:54	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 7210095699-01 // 29-3-2023 DRIVE IN/EXCESS : 31-3-2023 // SLD1801K - EQ DATE IN/DATE SURVEY: 10-4-2023 // TAUFIKH - LKK DIRECT SETTLEMENT BY: 4-4-2023 // NEO JIE SI - EQ X RH/HEADLAMP UNIT					1.00	3361.30	00.00	3361.30

Confirmed & accepted by

8% GST on **3361.30** **268.90**  
**Nett 3,361.30**  
**Total Payable 3,630.20**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG