

ASSIGNMENT



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNB4393M

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

Vehicle & Document Information

WIP No 64027
Reg No/Reg Date SNB4393M / 23/08/2021
Date In/Mileage / 0
Chassis No W1N2476842W1208263
Engine No 28291480528077
Make/Model MB/GLB 180
Colour/Trim 021 191 Cosmos Blac/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WE000058	Credit	31/03/2023/ 17:50	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPN SUN				
POLICY NO/ACC DATE : 7210095699-01 // 29-3-2023				
DRIVE IN/EXCESS : 31-3-2023 // SLD1801K - EQ				
DATE IN/DATE SURVEY:				
DIRECT SETTLEMENT BY:				
A BPILAB				1440
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				2400.00
A BPIRES				1600
RESPRAY FRONT BUMPER & RH/FRONT FENDER				1800.00
A BPILAB			0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				
A 97250001				180.00
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM				
M RH/FRONT FENDER	1.00	1479.57	00.00	1479.57
M RH/FRONT COVER, FENDER & BUMPER AREA	1.00	268.90	00.00	268.90
M FRONT BUMPER	1.00	1240.82	00.00	1240.82
M LH/UPPER BASIC CARRIER FOR BUMPER	1.00	53.72	00.00	53.72
M RH/UPPER BASIC CARRIER FOR BUMPER	1.00	62.80	00.00	62.80
M FRONT BUMPER BOTTOM BLACK TRIM COVER	1.00	260.96	00.00	260.96
M CAVITY PRESERVATIVE	1.00	116.39	00.00	116.39
M RIVET FOR BUMPER	10.00	5.34	00.00	53.40

Tan/lin 97495749
WP 10/4/23 1215
plp Resurvey before paint
tan/lin C/lin auto.com

* RH headlamp coat

Go Chee Han
DID : 6771 4336 HP 9151 7717
Email : cheehan.gom@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Center Pandan Loop

Confirmed & accepted by

04 days

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document. Confirms the estimated costs quoted are excluding GST. We would mention that the above estimate is based on visual inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without prejudice" basis

Nett 8,416.56
8% GST on 8416.56 673.32
Total Payable 9,089.88

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg