



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLD7373P

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT  
6 RAFFLES QUAY  
#21-00  
SINGAPORE 048580  
65073848

### Vehicle & Document Information

WIP No **64036**  
Reg No/Reg Date **SLD7373P / 31/05/2018**  
Date In/Mileage **/ 0**  
Chassis No **WDD2130422A435551**  
Engine No **27492031439409**  
Make/Model **MB/MB E 200 2.0 SEDAN (W213) "EXCLUSIVE/"**  
Colour/Trim **021 197 Obsidian Bl/ 048 801 Nappa Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	02/04/2023/ 19:26	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :1800056959 // 30-03-2023 DRIVE IN:30-03-2023 // TP CAR NO:SHB5235B (MS FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				1440.00
A BPIRES RESPRAY FRONT BUMPER			0.07	1000.00
M LH/F HEADLAMP	1.00	3677.73	00.00	3677.73
M FRT BUMPER	1.00	1709.58	00.00	1709.58
M LH/F BASIC MOUNTING FOR BUMPER	1.00	100.52	00.00	100.52
M LH/F BUMPER BRACKET	1.00	12.57	00.00	12.57
M LH/F BOTTOM GRILLE	1.00	122.51	00.00	122.51
M LH/F BOTTOM GRILLE GARNISH	1.00	86.70	00.00	86.70
M FRT CROSS MEMBER	1.00	579.46	00.00	579.46
M LH/F CROSS MEMBER BRACKET	1.00	35.50	00.00	35.50

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **9,264.57**  
8% GST on **9264.57** **741.17**  
**Total Payable 10,005.74**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG