

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7995H

MAKE REG.30.09.2020

MODEL : HYU IONIQ G2

DATE 01.02.2023

CHIANG/INCOME

MODEL	: HYU IONIQ G2		CHASSIS/VERSION		
Qty	Parts Description/ Labour		Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH				\$55.80
1	FRONT BUMPER				\$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING				\$368.50
1	FRONT BUMPER GRILLE LH				\$186.50
1	FRONT DAY LIGHT LH				\$642.50
1	FRONT FENDR SHIELD LH				\$164.70
1	HEAD LAMP LH				\$2,110.30
1	FRONT FENDER LH				\$588.80
1	FRONT FENDER EMBLEM				\$26.60
	SUB TOTAL				\$4,624.80
	20.00%				\$924.96
	DISCOUNTED TOTAL				\$3,699.84
	Labour Charge				
	Panel Beating				\$750.00
	Spray Paint				\$600.00
	Reset Front Wheel Alignment				\$60.00
	Check lighting				\$60.00
	TOTAL LABOUR				\$1,470.00
	ESTIMATE TOTAL				\$5,169.84
	Taufik 97495747				
	wp 2/2/23 @ 330				
	His house after repair				
	Taufik @ LK Auto				
	2 days				

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5790460


JC NO.305544347

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)
(P)
COUNT CARD NO.

REGN NO:	SHA7995H	MILEAGE
MAKE:	HYUNDAI	FUEL E.....1/2.....F
MODEL	IONIQ(G3)	DATE/TIME IN 01.02.2023 15:10
YR OF MANU.	30.09.2020	TARGET DATE
CHASSIS CODE	KMHC851CVLU190091	COMPLETION DATE/TIME:

Accident Date: 01.02.2023
NATURE: 3P 01.02.2023

S/NO LABOR CODE DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledge ment Slip

Exit Pass

e No.: SHA7995H CHIANG

Vehicle No.: SHA7995H

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard