

NS/INC23003479/Tnp3

REF:

INC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / ☒ IF / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

Workshop Ins: \_\_\_\_\_

if \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: MT/1207984-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Ching

Vehicle: IN / OUT

Veh No: SHV7995H Yr Regn: 2020 / Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 212751 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: km MC851CVLH19091

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ Hub / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO, or

Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 2/2/23

Survey held at

Comfort Logg

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed lump sum \$2400 and 2 days  
(red, \$2769.84, 54%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 04/05/23

☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp

☐

: Interview

☐

: Tech. Insp

Report Formel:

Lump Sum / L.B.R. /

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHA7995H

MAKE REG.30.09.2020

MODEL : HYU IONIQ G2

DATE 01.02.2023

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH			\$55.80
1	FRONT BUMPER			\$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING			\$368.50
1	FRONT BUMPER GRILLE LH			\$186.50
1	FRONT DAY LIGHT LH			\$642.50
1	FRONT FENDR SHIELD LH			\$164.70
1	HEAD LAMP LH			\$2,110.30
1	FRONT FENDER LH			\$588.80
1	FRONT FENDER EMBLEM			\$26.60
	<b>SUB TOTAL</b>			<b>\$4,624.80</b>
	<b>20.00%</b>			<b>\$924.96</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$3,699.84</b>
	<b>Labour Charge</b>			
	Panel Beating			\$750.00
	Spray Paint			\$600.00
	Reset Front Wheel Alignment			\$60.00
	Check lighting			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,470.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,169.84</b>
<p>Taufik 97495747</p> <p>wp 2/2/23 @ 330</p> <p>His house after repair</p> <p>Taufik @ LK Auto</p> <p>2 days</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5790460


JC NO.305544347

STOMER  
/MS COMFORT TRANSPORTATION PTE LTD  
STOMER NO 7010045  
DRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (R) (O)  
(P)  
COUNT CARD NO.

REGN NO:	SHA7995H	MILEAGE
MAKE:	HYUNDAI	FUEL E.....1/2.....F
MODEL	IONIQ(G3)	DATE/TIME IN 01.02.2023 15:10
YR OF MANU.	30.09.2020	TARGET DATE
CHASSIS CODE	KMHC851CVLU190091	COMPLETION DATE/TIME:

Accident Date: 01.02.2023  
NATURE: 3P 01.02.2023

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA7995H CHIANG

Vehicle No.: SHA7995H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard