

MFORTDELGRO ENGINEERING PTE LTD PAIR ESTIMATE*

VEHICLE NO SHA7995H
MAKE REG.30.09.2020
MODEL : HYU IONIQ G2

DATE 01.02.2023

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH			m \$55.80
1	FRONT BUMPER			ok ✓ \$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING			Ry \$368.50
1	FRONT BUMPER GRILLE LH			x \$186.50
1	FRONT DAY LIGHT LH			u { c \$642.50
1	FRONT FENDR SHIELD LH			x \$164.70
1	HEAD LAMP LH			✓ \$2,110.30
1	FRONT FENDER LH			Ry \$588.80
1	FRONT FENDER EMBLEM			u ✓ \$26.60
	SUB TOTAL		2618	\$4,624.80
	20.00%		2094.40	\$924.96
	DISCOUNTED TOTAL			\$3,699.84
	Labour Charge			
	Panel Beating			375 \$750.00
	Spray Paint			500 \$600.00
	Reset Front Wheel Alignment			905 u x \$60.00
	Check lighting			30 \$60.00
	TOTAL LABOUR		2999.40	\$1,470.00
	ESTIMATE TOTAL		4582400	\$5,169.84
			2 delays	
	Taufhir 97495749 wp 2/2/23 c 330 Lb using after repair Taufhir c lha and b 02 days			
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			