



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22009726/Rny3e2-1	
			Date: 11/04/2023	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFB 6883Y	Veh. Inspected	SFL 3131B
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VP05/026363	Excess (\$)	0.00
	Assign From	HUEY NI	Assign Date	03/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY 2.0 A	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053BK4107020292	Colour	GREY
	Odometer	191064 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/10/2022	Inspection Date	05/10/2022
	Survey held at	HONG MOTOR SERVICES BLK 5035 ANG MO KIO IND PARK 2 #01-365 SINGAPORE 569538		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	