

CROSSBORDERS LL(

Advocates & Solicitors

Our Ref: Your Ref: TK.8180.2022.HONG-PD

SFB6883Y

BECEIVED 1 2 DEC 2022 LONPAC

S'PORE

MAIN OFFICE 133 NEW BRIDGE ROAD #23-03/04/05 CHINATOWN POINT SINGAPORE 059413

TEL: 6438 1323 FAX: 6438 2313

-8 DEC 2022

TO: LYE YOON SAN

Blk 330 Yishun Ring Road

#08-1436

Singapore 760330

22 22 22 VPOT 026363 Uploaded.

**WITHOUT PREJUDICE** 

BY CERTIFICATE OF

**POSTING** 

BY PDX

WITHOUT PREJUDICE

cc: Lonpac Insurance Bhd

(Motor Claims Dept) 300, Beach Road #17-04/06 The Concourse Singapore 199555

Dear Sirs

**RE: CLAIMANT: TAN CHER CHAY** ACCIDENT INVOLVING VEHICLES NO. SFL3131B & SFB6883Y ALONG 307 YISHUN RING ROAD MSCP DECK 2A LOT NO. 60 ON 02.10.2022

We are instructed by the abovenamed to claim damages against you in connection with an accident on 2 October 2022 at about 02:15 hours along 307 Yishun Ring Road MSCP Deck 2A Lot No. 60 involving our client's vehicle no. SFL3131B and vehicle registration number SFB6883Y driven by you at the material time.

We are instructed that the accident was caused by the negligence of you in the driving, management and control of vehicle registration number SFB6883Y.

As a result of the accident, our client's vehicle registration number SFL3131B was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Α		Damages		
	a. b.	Cost of Repairs Loss of Use (7 days x \$120.00 per day) (inclusive of Sunday and 2 days Pre-Repair Inspection Notice)	\$ \$	3,000.00
В	•	Disbursements		
		LTA Search Fees	\$	7.49
	b.	GIA Report Fees	\$	31.00 -
	C.	Survey Report Fees	\$	535.00 /
С		LEGAL COSTS (AT THIS STAGE)	\$	749.00
			\$	5,162.49

CONFIDENTIALITY CAUTION This document is for the addressee(s) only and may contain confidential information and/or may be SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

We enclose herewith copies of the following documents in support of our client's claim:-

- a) GIA Report & Traffic Police Report lodged our client (SFL3131B) with sketch plan together with photographs of our client's vehicle no. SFL3131B;
- b) GIA Report lodged by you (SFB6883Y) with sketch plan together with photographs of your motor vehicle no. SFB6883Y;
- c) Result of LTA search on your vehicle registration no. SFB6883Y;
- d) Repair Bill from Hong Motor Service;
- e) Vehicle Assessment Report & Invoice from United Appraisal and Management Pte Ltd;
- f) Fifty-Five (55) colour photographs depicting the damage to our client's motor vehicle no. SFL3131B;
- g) Vehicle Owner Particulars of our client's vehicle no. SFL3131B; and
- h) Disbursement Invoices.

We have on 3 October 2022 notified your insurers **Lonpac Insurance Bhd** of the accident and pre-repair inspection of our client's vehicle was carried out by your insurer.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter **within 14 days** of your receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks** of your receipt of this letter.

Yours\_faithfully

CrossBorders LLC

Email: corene@crossbordersllc.com (secretary)

encs

CC:

SFL3131B

SA1H22A30002 / AMK Autopoint Pte Ltd ENTRY DATE & TIME: 03/10/2022 11:22 (SGT) SUBMITTED BY: Joelle Tan VERSION: 1 (03/10/2022 11:22 (SGT))

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Actual Driver
   Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 03/10/2022 11:22 (SGT) Reported by Date of Accident ..... 02/10/2022 02:15 (SGT) Exact Location of Accident ..... 307 Yishun Ring Rd, Singapore 760307 Additional Location Information MSCP DECK 2A LOT NO. 60 Country/State of Loss Singapore **DETAILS OF OWN VEHICLE** Vehicle Registration Number SFL3131B INSURED/POLICYHOLDER Is company? No Name Of Registered Owner TAN CHER CHAY NRIC No ..... S1221692J Email Address tt\_trpservices@yahoo.com Mobile Phone No (Phone) +65-96637923 Alternative Phone No VEHICLE PARTICULARS Manufacturer Toyota Model Camry Variant ..... Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party Vehicle Category ..... Private car Transmission ..... Auto CC ...... 1998 INSURANCE COMPANY Name of Insurance Company ..... Income Insurance Limited Policy Number / Cover Note Number 5096121751-04 DRIVER Name of Driver TAN CHER CHAY

S1221692J

03/12/1956

Indoor

NRIC No .....

Date Of Birth

Occupation .....

Date, Of Driving Pass	22/06/1976
Driving experience	46 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96637923
Alt. Phone Number	-
Email Address	tt_trpservices@yahoo.com
Address	BLK 311 YISHUN RING ROAD #04-1268
Address complement	#
Postcode	760311
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	<b>.</b>
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
	-
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	His and man / Mandalians / Damana daybilet andred
Weather Conditions	Hit and run / Vandalism / Damaged whilst parked
Road Surface	Clear
Troad Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s)	U .
soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	
Translator's phone number	_
Translator's email	•
Original language used in the statement	•
Original language used in the statement	-
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	Van
Police Station Name	Yes Yishun North Neighbourhood Police Centre
Police Station Phone No	
Alt, Police Station Phone No	(Phone) +65-18008529999
Police Station Address	(Fax) +65-68522299
Was notice of intended Prosecution given?	31 Yishun Central Singapore 768827
If yes, against whom?	No -
CIRCUMSTANCES OF ACCIDENT	
PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes No
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number	SFB6883Y

Vehicle Model
Vehicle Variant

Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	-
Contact Number	_
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property demograd in posident	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### WITNESS DETAILS

#### WITNESS 1

Name		MR CHUA
Phone	***************************************	(Phone) +65-96675678
Email		(1 110116) 100-80073076

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

Centre Personnel's Signature Reporting

Joelle tan Name:

NRIC/FIN (10) Autopoint pre up ame 03.10. 2012

GROWC StetchFlexionor VI

DESCRIBE CIRCUMSTANCES OF T	HE ACCIDENT	Deck 2B
PLEASE REF	er to police report t	50321002/2069
ATTACHED.		
DECLARATION  I/We declare the foregoing particulars	are true in every respect.	j.
Policyhodicr's Signature Date & Time: GIABLIC Months in tous, 1/3	Oriver's Signature (if driver is not the policyholder) Oate & Time:	Reporting Contre Personnel's Signature Name: JOEILE TON NRIC/FIN No.: AMK AUTOPOINT PIE 4D 03.10.2022





























Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

l of 3 Report No. T/20221002/2069

REPORT OF	A TRAFF	IC ACCIDENT		•	
Date/Time Report Made: 02/10/2022 19:35			Vide Report No.:	Station Diary No.:	
Informan	t's Partic	ulars			
Name of Informant: TAN CHER CHAY			Address: APT BLK 311 YISHUN RING 760311	ROAD #04-1268 SINGAPORE	
ID Type / ID No.: NRIC NO / S1221692J  Nationality: SINGAPORE CITIZEN  Sex: Age: Date of Birth: Male 65 03/12/1956  Race: Chinese Occupation: Retiree			Contact No.: Home/Office:	Mobile: 96637923	
			Email:		
			Type of informant: Vehicle Owner	· management of the second of	
			Language: Chinese	Institution / School Name:	
			Driving Licence Information: Class: 3	Date of Expiry:	

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 02/10/2022 02:15	Type of Location: Car Park
Location: YISHUN RING	S POAD			•
	3 NOAD			
Weather: Clear		Road Surface: Dry	R	oad Speed Limit:
Traffic Flow:		Traffic Control:	T	raffic Volume:

Details of V	ehicle Invo	lved				
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passanger
SFB6883Y	Car	MERCEDES BENZ		Black		0
SFL3131B	Car	TOYOTA	Camry 2.0	Silver	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20221002/2069

Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

2 of 3 Report No. T/20221002/2069

CONTINUATION OF REPORT

Name	TAN CHER CHAY		<u></u>	ID No		S1221692J
Related Vehicle	SFL3131B (Car)	- 14:5 · · · · · · · · · · · · · · · · · · ·		Conta	ict No.	96637923
Hospital/Clinic	NIL			Class Drivin Licend Expire	g	Class: 3 Date of Expiry: NIL
Dale Treatment	NIL		Date Disc	harge	NIL	
No. of Days grant	led Medical Leave	NIL	Degree of		NIL	

#### **Brief Details**

On 01/10/2022 at about 9-10 in the evening, I have parked my car bearing registration number SFL3131B at the parking lot beside Lot No.: 59 (SG Blue parking lot) of Deck 2A of MSCP, Blk 307 Yishun Central and left to home. All was in order.

On 02/10/2022 at about 1030hrs, I returned to my car and discovered that the front number plate was dislodged and there were dents and scratches on the front bumper. There was also a slip of paper left on the windscreen of my car stating "I SAW WHO HIT YOUR CAR PLS CALL ME @ 96675678". I had then contacted the said number on the paper, the person informed that a black Mercedes bearing registration number SFB6883Y had collided to my car while making a right turn. I checked around the said carpark and spotted the said vehicle SFB6883Y with scratches, slight dent with white paint marks on its front left portion bumper.

I am lodging this report for insurance claimant and hit-and-run investigation. My car is installed with dashcam, however it is not operational when the engine is switched off.





Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

3 of 3 Report No. T/20221002/2069

CONTINUATION OF REPORT

Informant is not able to pro	vide sketch plan

Sketch Plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: L / SR STAFF SGT YAP YHEE HOE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/10/2022 19:35
Officer In Charge Of Case: TP / HRT / SR STAFF SGT NEO ZHI YUAN Contact No.: 65476079	Classification Of Case:
NP168	

( )

SC1122AB000B / CHENG HOE MOTOR PTE LTD[768761] ENTRY DATE & TIME: 11/10/2022 18:11 (SGT) SUBMITTED BY: CHIONG BENG CHOON VERSION: 1 (11/10/2022 18:11 (SGT))

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE -

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 11/10/2022 18:11 (SGT) Reported by Date of Accident ..... 02/10/2022 02:15 (SGT) Exact Location of Accident ..... Singapore Additional Location Information ..... 307 YISHUN RING RD (MSCP) DECK 2A Country/State of Loss Singapore **DETAILS OF OWN VEHICLE** Vehicle Registration Number SFB6883Y INSURED/POLICYHOLDER Is company? Name Of Registered Owner LYE YOON SAN VEHICLE PARTICULARS Manufacturer ..... Model ..... E200 EXCLUSIVE (R18 LED) Variant ..... Vehicle Category Private car Transmission ..... Auto CC ..... 1991 INSURANCE COMPANY Name of Insurance Company ..... Lonpac Insurance Bhd Policy Number / Cover Note Number Z22VP05031963 DRIVER

LYE YOON SAN

BLK 330 YISHUN RING ROAD #08-1436

S26705951

760330

Nο

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... No Collision

Name of Driver

NRIC No

Address .....

Address complement ..... Postcode .....

Does Driver Own Other Vehicles?

Was any foreign vehicle involved in the accident?  Was any body injured in the Accident?  Was any other vehicle or property damaged?  Number of Passengers (Including Driver)  Translator's name  Translator's ID  Translator's phone number  Translator's email  Original language used in the statement  REFER ATTACHED  ATTACHMENT(S)	Weather Conditions	Shelter
Was any other vehicle or property damaged?  No Was any other vehicle or property damaged?  Number of Passengers (Including Driver)  Translator's name  Translator's ID  Translator's phone number  Translator's email  Original language used in the statement  REFER ATTACHED	OTHER INFORMATION	
REFER ATTACHED	Was anybody injured in the Accident? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Translator's name Translator's ID Translator's phone number Translator's email	No
	CIRCUMSTANCES OF ACCIDENT	
ATTACHMENT(S)	REFER ATTACHED	
	ATTACHMENT(S)	

## DETAILS OF OTHER VEHICLE PROPERTY 1

Yes

Yes

FOOTAGE IS CAPTURE

GOT INSTALL CAR CAMERA BUT NOT SURE IF ACCIDENT

Vehicle Registration Number	SFL3131B
Vehicle Manufacturer	OI LOIDID
	-
Vehicle Model	-
Vehicle Variant	_
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	-
Insurance Company Name	

Are accident photos available for attachment?

Was there any video captured by Car Camera? .....

Reasons for not uploading a video of the accident .....

VEHINO

SEB 68837

#### IMPORTANT NOTICE

INSURFR League

DATE OF ACC: 2/10/22 2:15am

1. Please report <u>comming</u> the details of the accident to speed up the claims process

This Form must be completed by the Petcyholder and/or the Actual Direct
 Information provided must be as <u>Eurobled and accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurance companies to <u>reputified policy habitity</u>.

SKETCH PLAN

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy fability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers tewyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the maxing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of chain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable tew in administering, processing, handling end/or dealing with my claims.
 (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (uncluding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Senature / Date & Time

Driver's Signature (if driver is not the posicyholder) / Date

(YS) ag 11 (0 2.2 Witnessed by Reporting Centre Personne: (Name as in NRIC/ID card)

Sketch Plan

PLEASE

OVER

OVER

1

Describe Circumstance of the Accident	Low	~		
" NOTE PLEASE TAKE NOTE THAT YOUR IN				WN DAMAGE
Claim under your Own Comprehensive p		2	_	
ा । विकास के किया किया किया किया किया किया किया किया	m Third party	( / )	Reporting Onl	∠gu
( ) Claim OD/ TP at other workshop (_ Sketch Plan			. 1	
oxelen righ				
307 Nishun	Ring Rd	(MSCA)		4 C Q T Y
Deck 2A			A: SFB	68621
, i	`   <del></del>	<u></u>	BSFL	21710
	.   <del> </del>			1111
		Na a la		
		2	, ;	
Control of the contro		406	1: 2/10/22	2.15 am
The state of the s				
After going up the ram	p I pack	my veh	icle as u	s.u.a.
72		L A	,	
I did not felt any imp	M.C.T. No. Jan. 10	: Cacle A actor.	CMG() (FB)	7
Loopac Tosurance Ms. Eng	from Loo	امد (د	204)	called
The one of the second s	]			
me on 2/10/22 to file =	ccident KEA	or <u>≠ -</u>	Soon IS po	<u></u>
	,	, <u>, , , , , , , , , , , , , , , , , , ,</u>		
			. ,	
		***************************************		
		marin material felo della dell		
Declaration		<del></del>		
RMe decrate the totodoing barrichtars are tine to exert, to preceduation.	spect.			
Z SW	M*************************************		چوم (۲۲)	<u>دراماب</u>
Policyholder's Signature / Date & Time Driver's Signature & Time	(if driver is not the policyholde		Witnessed by ReportiQ C Name as in NRICAD card	

2



## Enquire Vehicle's Insurance Particulars (As At 02 Oct 2022 / 02:15:00)

Vehicle No.:

Make Description/Model:

SFB6883Y

MERCEDES BENZ / E200 EXCLUSIVE (R18 LED)

Insurance Company Name:

LONPAC INSURANCE BHD

Business Transaction Reference No.:

20221003142847595568

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Printed on 03 Oct 2022 14:29:13

Copyright © Land Transport Authority of Singapore 2022

# 鴻汽車修理 HONG MOTOR SERVICE

5035 Ang Mo Kio Ind. Park 2, (off avenue 3), #01-365 Singapore 569538
TEL: 6282 2052 Fax: 6556 2934

HP: 94507061

Name

: TAN CHER CHAY

Address

: c/o Hong Motor Service

Blk 5035 Ang Mo Kio Ind. Park 2

#01-365

Singapore 569538

Date : 21 Nov 2022

Invoice no. : HMS/SFL3131B

DOA: 02/10/2022

FINAL REPAIR BILL FOR TOYOTA CAMRY 2.0 AUTO ABS AIRBAG no. SFL3131B

Lump Sum Repair cost

\$ 3,000.00

SINGAPORE DOLLARS: THREE THOUSAND ONLY



No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874 Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg Business Registration Nos.: 200817301N

## **INVOICE**

To: Tan Cher Chay

Date

: 21 Nov 2022

c/o : Hong Motor Service

Blk 5035 Ang Mo Kio Ind. Park 2

Invoice No.: 8094353

#01-365

Singapore 569538

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 535.00
Photographs 55 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 535.00
Singapore dollar : FIVE HUNDRED THIRTY FIVE ONLY.	
Registration no. : SFL3131B	
Make/Model : Toyota Camry 2.0 Auto Abs Airbag	
Our reference : UAM22.10.03-MF-STP-HMS-SFL3131B	
All payments made payee to:-	
" UNITED APPRAISAL & MANAGEMENT PTE LTD"	

for UNITED APPRAISAL & MANAGEMENT PTE LTD

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874
Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg
Business Registration Nos.: 200817301N

Our ref.: UAM22.10.03-MF-STP-HMS-SFL3131B

Date : 21 Nov 2022

Tan Cher Chay

M. Farez

Encls.:

Motor Vehicle Appraiser

WITHOUT PREJUDICE Dear Sir. Re: Third Party Claim For Vehicle Registration No. **SFL3131B** We refer to your instruction to appraise the above-mentioned vehicle or 05 October 2022 A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Hong Motor Service as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly. Our revised quotation for the repair is SGD 3,769.79. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced. We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for **SGD 3,000.00** NETT. Which, in our opinion is fair and reasonable. The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs. Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 4 (Four) days. We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered. Please do not hesitate to contact us if you have any queries on this matter. Yours faithfully, United Appraisal & Management Pte Ltd

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

# UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874
Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg
Business Registration Nos.: 200817301N

#### VEHICLE INSPECTION REPORT

To: Tan Cher Chay

Our ref.: UAM22.10.03-MF-STP-HMS-SFL3131B

Date : 21 Nov 2022

#### REFERENCE

Assign by	:	Tan Cher Chay	Insured	:	To be advice
Assign on	:	05 Oct 2022	Policy no.	:	To be advice
Inspection on	:	05 Oct 2022	Claim no.	:	To be advice
Accident on	:	02 Oct 2022	Sum insured	:	To be advice
Workshop name	:	Hong Motor Service	Excess	:	Not applicable
Inspection at	:	Blk 5035 Ang Mo Kio Ind. Park 2	3rd party Veh.	:	To be advice
		#01-365	3rd party ins.	:	To be advice

Singapore 569538

#### PARTICULARS OF DAMAGED VEHICLE

Registration no. : SFL3131B Odometer : 191064 km

Make / Model : Toyota Camry 2.0 Auto Abs Airbag Chassis no. : MR053BK4107020292

Regn. date : 02 Jan 2008 Engine no. : 1AZE069992 Body colour : Silver Engine cap. : 1998 cc

#### PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	:	In order	Paintwork	:	Good
Footbrake	:	In order	Undercarriage	;	Serviceable
Handbrake	:	In order	Gen. condition	:	Good


#### TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Bridgestone	215/60R16	70%	Alloy
Front O/S	:	Bridgestone	215/60R16	70%	Alloy
Rear N/S	:	Bridgestone	215/60R16	70%	Alloy
Rear O/S	:	Bridgestone	215/60R16	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

<sup>\*</sup> Denotes damaged component/s

#### POINT OF IMPACT



## SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the front bumper, front grille, brace panel and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 18 Oct 2022 for repair in progress.

#### RECOMMENDATION

The estimate cost of repair submitted by Messrs Hong Motor Service as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 3,000.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

#### REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 4 (Four) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,

M. Farez

United Appraisal & Management Pte Ltd

Motor Vehicle Appraiser

## APPRAISEMENT SCHEDULE


Annex A


Registration no.
Our reference

: SFL3131B


: UAM22.10.03-MF-STP-HMS-SFL3131B

LIST ITEMS   1	S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
1   Front bumper   Deformed   1157.00   1157.00   2   2   Front bumper side retainer @ SGD 131.60   Necessary   263.20   263.20   263.20   3   1   Front bumper reinforcement   Serviceable   S20.40   0.00   0.00   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   288.30   275.00   275.	<del></del>		LIST ITEMS		- 1	11110001
2   Front bumper side retainer @ SGD 131.60   Necessary   263.20   263.20   3   1   Front bumper rinforcement   Serviceable   520.40   0.00   4   1   Front bumper inner sponge   Torn   288.30   288.30   5   1   Front bumper centre lower grille   Cut/Deformed   275.00   2				D 6 1	1157.00	11.55.00
1   Front bumper reinforcement   Serviceable   520.40   0.00     4   1   Front bumper reinforcement   Tom   288.30   288.30     5   1   Front bumper centre lower grille   Cut/Deformed   275.00   275.00     6   1   Front bumper lower cover o/s   Cut   195.30   195.30     7   1   Front bumper lower cover n/s   Cut   187.55			<del>-</del>			
1   Front bumper cinner sponge   Torn   288.30   288.30   288.30   5   1   Front bumper centre lower grille   Cut/Deformed   275.00   275.00   275.00   6   1   Front bumper lower cover o/s   Cut   195.30   10   1   Front grille logo   Necessary   65.50						
Front bumper centre lower grille						
6         1         Front bumper lower cover o/s         Cut         195.30         195.30           7         1         Front bumper lower cover n/s         Cut         187.55         187.55           8         1         Front grille         Cracked         504.20         504.20           9         1         Front grille logo         Necessary         65.50         65.50           10         1         Front brace panel         Bent         217.00         217.00           3         1         Front brace panel         Less         0% / 25%         0.00         788.26           3         3673.45         3153.05         3153.05         3153.05         2364.79           SPECIAL NETT ITEMS         Less         0% / 25%         0.00         788.26           SPECIAL NETT ITEMS         Less         Necessary         50.00         30.00           2         1 set         Front bumper clips         Necessary         50.00         30.00           3         1 set         Front grille clips         Necessary         40.00         40.00           4         1 Front mumber plate with casing         Necessary         40.00         215.00			, , ,			
Total Pront bumper lower cover n/s						
Front grille   Cracked   504.20   504.20   9   1   Front grille logo   Necessary   65.50   6			_			
Pront grille logo   Necessary   65.50   65.50   10   1			<del>-</del>			
Less   O% / 25%   0.00   788.26						
Less   0% / 25%   0.00   788.26			•	•		
SPECIAL NETT ITEMS   3673.45   2364.79	10	1	Tront orace paner	Done		3153.05
SPECIAL NETT ITEMS   3673.45   2364.79				T one 00/ / 250/	0.00	700 76
1   1   Sundries   Necessary   50.00   30.00     2   1   1   Steel   Front bumper clips   Necessary   80.00   80.00     3   1   1   Front number plate with casing   Necessary   40.00   40.00     4   1   Front number plate with casing   Necessary   70.00   65.00     2   2   2   2   2   2   2   2     1   To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.     2   To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.     3   To apply undercoating on the accident repair and replaced panel for rust protection.     4   Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.     TOTAL   1780.00   1190.00     Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)   769.79				LUSS 070/2370		
1   1   Sundries			SPECIAL NETT ITEMS		3013.73	2304.19
1 set   Front bumper clips   Necessary   80.00   80.00     3   1 set   Front grille clips   Necessary   40.00   40.00     4   1   Front number plate with casing   Necessary   70.00   65.00     240.00   215.00     240.00   215.00     240.00   215.00     TOTAL   3913.45   2579.79     LABOUR & MISC CHARGES     1   To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.     2   To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.     3   To apply undercoating on the accident repair and replaced panel for rust protection.     4   Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.     TOTAL   1780.00   1190.00     Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)   769.79	1	1		Managamy	50.00	20.00
1   Front number plate with casing   Necessary   40.00   40.00   40.00   40.00   40.00   240.00   215.00   240.00   215.00   240.00   215.00   240.00   215.00   240.00   215.00   240.00   215.00   240.00   215.00   240.00   215.00   240.00   215.00   3913.45   2579.79				_		
TOTAL  To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.  To apply undercoating on the accident repair and replaced panel for rust protection.  Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.  Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)  TOTAL  TOTAL  TOTAL  Supply spray paint material adjustment)  Necessary 70.00 65.00 240.00 215.00 240.00 215.00 3913.45 2579.79  80.00 600.00 350.00 400.00 600.00 600.00 600.00 400.00 600.00 600.00 600.00 600.00 400.00 600.00 600.00 600.00 600.00 600.00 600.00 600.00 600.00 6				•		
TOTAL  TOTAL  240.00 215.00 3913.45 2579.79  LABOUR & MISC CHARGES  1 To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.  2 To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.  3 To apply undercoating on the accident repair and replaced panel for rust protection.  4 Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.  TOTAL  1780.00 1190.00  Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 5693.45 3769.79			- "	-		
LABOUR & MISC CHARGES  1 To dismantle / renew the accident damaged SGD 350.00/day 600.00 350.00 portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.  2 To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.  3 To apply undercoating on the accident repair and replaced panel for rust protection.  4 Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.  TOTAL 1780.00 1190.00  Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 5693.45 3769.79	4	1	From humber plate with casing	inecessary		
To dismantle / renew the accident damaged SGD 350.00/day 600.00 350.00 portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.  To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.  To apply undercoating on the accident repair and replaced panel for rust protection.  Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.  TOTAL 1780.00 1190.00  Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 5693.45 3769.79			TOTAL			2579.79
portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.  2 To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.  3 To apply undercoating on the accident repair and replaced panel for rust protection.  4 Supply spray paint material and necessary items SGD 300.00/pnl 900.00 600.00 to respray bonnet front bumper and other affected area / panel.  TOTAL 1780.00 1190.00  Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 5693.45 3769.79			LABOUR & MISC CHARGES			
component to facilitate repairs, reconnect and check functions.  To apply undercoating on the accident repair and replaced panel for rust protection.  Supply spray paint material and necessary items to respray bonnet front bumper and other affected area / panel.  TOTAL  South Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)  5693.45  3769.79	1		portion. To panel beating, reshape, straighten	,	600.00	350.00
and replaced panel for rust protection.  4 Supply spray paint material and necessary items SGD 300.00/pnl 900.00 600.00 to respray bonnet front bumper and other affected area / panel.  TOTAL 1780.00 1190.00  Total Parts and Labour Cost of Repair 5693.45 3769.79 Less (Lumpsum repair adjustment) 769.79	2		component to facilitate repairs, reconnect and	1	80.00	60.00
to respray bonnet front bumper and other affected area / panel.  TOTAL  1780.00  1190.00  Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)  5693.45  769.79	3				200.00	180.00
Total Parts and Labour Cost of Repair 5693.45 3769.79 Less (Lumpsum repair adjustment) 769.79	4		to respray bonnet front bumper and other affecte	*	900.00	600.00
Less (Lumpsum repair adjustment) 769.79	<del></del>		TOTAL		1780.00	1190.00
Adjustment Parts and Labour Cost of Repair 3000.00	<u></u>		_		5693.45	3769.79 769.79
			Adjustment Parts and Labour Cost of Rep	air		3000.00


























































































































## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	692J
Vehicle Details	
Vehicle No.:	SFL3131B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1AZE069992
Chassis No.;	MR053BK4107020292
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$26,830.00
Original Registration Date:	02 Jan 2008
First Registration Date:	02 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$29,513.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$50,168.00
COE Rebate Amount:	\$25,878.00
Total Rebate Amount:	\$25,878,00

The information contained herein is correct as at 03 Oct 2022



You have successfully logged out.

Your last login date and time was 03 Oct 2022, 14:25:28.

To return to ONE.MOTORING, please click here

For security reasons, please CLEAR YOUR CACHE after each session.

#### **Session Transaction History**

S/No.1=	Asset Type≎	Asset ID‡	Transaction Type≎	Transaction Amount(S\$)≎	Log Date/Time≑
1	Vehicle	SFB6883Y	18.19 Enquire Veh Owner Info (Others) by Law Firm		03 Oct 2022 / 14:28:47



## GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

9 Temasek Boulevard, Suntec City Tower Two #42-01B Singapore 038989

E-mail: gears-support@shift-technology.com GST Registration: M400017735

## TAX INVOICE

Date of Request: 14/10/2022 Your Ref No: HONG.SFL3131B

Dear Sir/Madam,

Date of Accident: 02/10/2022 00:00 (SGT)

Vehicle No: SFL3131B Place of Accident: Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION		PER DOC (S\$)	QTY	AMOUNT (S\$)	
SFB6883Y	Singapore		(31.00)	1	(28.97)	
GST Amount						
Total Amount Due	(GST Inclusive)				(31.00)	

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.