

**Cheng Auto Bodyworks** (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

|                     |                       |                       |            |
|---------------------|-----------------------|-----------------------|------------|
| Claim Type:         | OD (OWN DAMAGE)       | Ref. No:              |            |
| Policy No:          | SPCM1000000252        | Date of Loss:         | 19/03/2023 |
| Vehicle Reg. No.:   | YQ7144L               | Driveable?            |            |
| Driver Age/Info:    |                       | Party At Fault:       | UNKNOWN    |
| TP Injury Involved? | NO                    | Third Party Involved? | YES        |
| Insured/Claimant:   | JOKIA PRIVATE LIMITED |                       |            |

|                 |                                             |                    |                   |
|-----------------|---------------------------------------------|--------------------|-------------------|
| Make/Model:     | HINO XZU710R, 4.0 D 14FT WIDE<br>CAB 5T (M) | Vehicle Reg. Date: | 27/05/2022        |
| Vehicle Colour: | WHITE                                       |                    |                   |
| Engine No:      | N04CWN18199                                 | Chassis No:        | JHHUCV3F10K044239 |
| Odometer:       | 1 KM                                        |                    |                   |

Paint Type:

Total Loss?

NO

Est. Duration of Repair  
(day)~~4~~ 3

Present Location: CHENG AUTO BODYWORKS (HQ)

**COST OF CLAIMS**

|                          | Amount          |
|--------------------------|-----------------|
| Parts                    | 4,295.50        |
| Miscellaneous Items      | 0.00            |
| Labour                   | 1,800.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>6,095.50</b> |
| <b>+ GST 8.00% (S\$)</b> | <b>487.64</b>   |
| <b>Nett Amount (S\$)</b> | <b>6,583.14</b> |

This claim is handled by: MURUGESAN S/O REGUNATHAN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 31 Mar 2023)**Parts:** N/A HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Auto Bodyworks/YQ7144L/31/03/2023 18:26**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No. | Qty | Part No. | Particulars                | %Disc | %Depr | Amount          |
|-----|-----|----------|----------------------------|-------|-------|-----------------|
| 1   | 1   |          | *DOOR RH                   | 0.00  | 0.00  | *1,550.00 F, DT |
| 2   | 1   |          | *DOOR RH HINGE UPPER       | 0.00  | 0.00  | *60.00 F, NN    |
| 3   | 1   |          | *DOOR RH HINGE LOWER       | 0.00  | 0.00  | *60.00 F, NN    |
| 4   | 1   |          | *DOOR LOCK ASSY            | 0.00  | 0.00  | *350.00 F, NN   |
| 5   | 1   |          | *DOOR LH SIGNAL LAMP       | 0.00  | 0.00  | *60.00 F, BR    |
| 6   | 1   |          | *HEADLAMP RH               | 0.00  | 0.00  | *550.00 F, SCR  |
| 7   | 1   |          | *RH SIDE MIRROR STAND ASSY | 0.00  | 0.00  | *220.00 F, DT   |
| 8   | 1   |          | *RH SIDE PARKING MIRROR    | 0.00  | 0.00  | *120.00 F, CRA  |
| 9   | 1   |          | *STEP GARNISH RH           | 0.00  | 0.00  | *220.00 F, NN   |
| 10  | 1   |          | *FRT BUMPER                | 0.00  | 0.00  | *450.00 F, CRA  |
| 11  | 1   |          | *FRT BUMPER BRACKET RH     | 0.00  | 0.00  | *190.00 F, DIS  |
| 12  | 1   |          | *FOGLAMP RH <i>missing</i> | 0.00  | 0.00  | *75.00 F        |

F=Franchise part.

Sub Total (\$\$) 3,905.00

+ Margin on L,N Items 10.00% (\$\$) 390.50

Total Parts (\$\$) 4,295.50

Cheng Auto Bodyworks/YQ7144L/31/03/2023 18:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                              | Particulars                                                                      | Lab.Type | Amount          |
|---------------------------------|----------------------------------------------------------------------------------|----------|-----------------|
| <b>Labour Items</b>             |                                                                                  |          |                 |
| 1                               | LABOUR                                                                           | New      | 600 800.00      |
| 2                               | SPRAYPAINTING                                                                    | New      | 600 800.00      |
| 3                               | DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR | New      | 100 200.00      |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                  |          | <b>1,800.00</b> |

Cheng Auto Bodyworks/YQ7144L/31/03/2023 18:26. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

REPAIR 3 DAYS

→ NOT AUTHORISE

- EXCESS \$600

- P/P OR L/S REPAIR?

- SURVEY BY EDWARD TEL 62563561

- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: