

# Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub  
Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003321854	Date of Loss:	31/03/2023
Vehicle Reg. No.:	<b>SLV2913U</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM JING KAI		

Make/Model:	AUDI A4, 1.8 TFSI MU (EU6) (A)	Vehicle Reg. Date:	30/06/2014
Vehicle Colour:	BLACK		
Engine No:	CJE077173	Chassis No:	WAUZZZ8K5EA119393
Odometer:	157440 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	7

Present Location: WAH HONG MOTORS & CREDIT PTE LTD (HQ)

## COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	16,945.50
Labour	1,015.00
Paintwork Labour	2,790.00
Towing	0.00
	0.00
<b>Gross Total (S\$)</b>	<b>20,750.50</b>
<b>+ GST 8.00% (S\$)</b>	<b>1,660.04</b>
<b>Nett Amount (S\$)</b>	<b>22,410.54</b>

This claim is handled by: **THONG ZHONGMING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2023)  
 Parts: 143 AUDI A4 1.8 TFSI MU (EU6) (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/04/2023 14:44  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Headlamp LH <i>See /</i>	0.00	0.00	*1,200.00 F
2	1		*Headlamp lower bracket LH ?	0.00	0.00	*90.00 F
3	1		*Front bumper <i>See /</i>	0.00	0.00	*1,250.00 F
4	1		*Front bumper side retainer RH/LH @2*\$25 <i>See /</i>	0.00	0.00	*50.00 F
5	1		*Tower cover LH <i>X</i>	0.00	0.00	*35.00 F
6	1		*Front fender shield LH <i>See /</i>	0.00	0.00	*140.00 F
7	1		*Front upper arm forward RH/LH @2*\$350 ?	0.00	0.00	*700.00 F
8	1		*Front upper arm rear RH/LH @2*\$350 ?	0.00	0.00	*700.00 F
9	1		*Front lower arm RH/LH @2*\$350 ?	0.00	0.00	*700.00 F
10	1		*Front lower arm ball joint RH/LH @2*\$150 ?	0.00	0.00	*300.00 F
11	1		*Front control arm RH/LH @2*\$650 ?	0.00	0.00	*1,300.00 F
12	1		*Front absorber RH/LH @2*\$850 ?	0.00	0.00	*1,700.00 F
13	1		*Front absorber bracket RH/LH @2*\$200 ?	0.00	0.00	*400.00 F
14	1		*Front absorber top mounting RH/LH @2*\$70 ?	0.00	0.00	*140.00 F
15	1		*Front tie rod end RH/LH @2*\$120 ?	0.00	0.00	*240.00 F
16	1		*Front rack end RH/LH @2*\$140 ?	0.00	0.00	*280.00 F
17	1		*Front linkage RH/LH @2*\$120 ?	0.00	0.00	*240.00 F
18	1		*Front anti roll bar bushing RH/LH @2*\$20 ?	0.00	0.00	*40.00 F
19	1		*Front fender RH/LH @2*\$550 <i>See /</i>	0.00	0.00	*1,100.00 F
20	1		*Front crossmember ?	0.00	0.00	*2,850.00 F
21	1		*Front anti roll bar ?	0.00	0.00	*340.00 F
22	1		*Fog lamp Cover RH/LH @2*\$85 <i>See /</i>	0.00	0.00	*170.00 F
23	1		*Front fender LH <i>X repeated</i>	0.00	0.00	*550.00 F
24	1		*Lower engine front cover (front) <i>See /</i>	0.00	0.00	*450.00 F
25	1		*Lower engine front cover (Rear) <i>See /</i>	0.00	0.00	*440.00 F
26	1		*Front fender RH (Refer refer to labour)	0.00	0.00	*- F
27	1		*Bonnet (Refer refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$\$)	15,405.00
+ Margin on L,N Items 10.00% (\$\$)	1,540.50
<b>Total Parts (\$\$)</b>	<b>16,945.50</b>

Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/04/2023 14:44. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	Engine lower cover clips <i>new</i>	30 <del>50.00</del>
2	1	Front bumper clip <i>new</i>	35.00
3	1	Front fender shield clip LH <i>new</i>	30.00
4	1	Front rim LH 19 <i>new</i>	900.00
<b>Sub Total (\$\$)</b>			<b>1,015.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	800 <del>1,000.00</del>
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800 <del>1,000.00</del>
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	80 <del>60.00</del>
4	To check and wheel computerize adjustment	New	60 <del>80.00</del>
5	Remove and replace front undercarriage RH/LH @2*\$200 <i>photo</i>	New	300 <del>400.00</del>
6	Remove and replace steering rack <i>photo</i>	New	100? <del>200.00</del>
7	To remove and replace front rim LH and wheel balancing	New	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,790.00</b>

**Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/04/2023 14:44. Not valid without Reference section.**  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Panel  
 Hp 90010068  
 8 days  
 L/S  
 04/04/23 @ 1430  
 excess: 600  
 Repair  
 Resy after repair