



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS/HSB23003488/Uqp3m4 Date: 28/04/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 5297L	Veh. Inspected	GBD 896L	
Policy No.	VFX/P2413997	Coverage (\$)	0.00	
Claim No.	S3M04KY8	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	03/04/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ CITAN 109 CDI (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDF4156052U140335	Colour	SILVER	
Odometer	137689 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65R15	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	24/03/2023	Inspection Date	04/04/2023	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	