

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road,#17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josephine Wong

Date: 14 Apr 2023

Preliminary Advice

Insured Vehicle No	: SLZ8025Y		
TP Vehicle No	: SNB1724L	Accident Date	: 03/04/2023
Make	: TOYOTA VIOS	Assignment Date	: 04/04/2023
Date of Inspection	: 04/04/2023	Est. Duration of Repair	: 07
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,858.10
Revised Amount	:S\$	2,955.30
Check Items (Estimated)	:S\$	
Total	:S\$	2,955.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a "Without Prejudice" basis.
- Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.