

AUTOMOBILE HUB ENTERPRISE

VEHICLE DETAILS

VEHICLE NO : PC6694C 2017 OCT
 VEHICLE MODEL : TOYOTA HIACE COMMUTER
 CHASSIS NO : KDH2230030293

TP Ego.

Celina.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Det</i>	1	\$ 479.80	\$ 479.80
2	REAR BUMPER SIDE HOLDER <i>RW Det</i>	1	\$ 58.40	\$ 58.40
3	TAILLAMP <i>Unit</i>	1	\$ 389.40	\$ 389.40
4	REAR BODY PANEL <i>Det</i>	1	\$ 1,715.90	\$ 1,715.90
5	REAR BODY PANEL AIR VENT <i>Item</i>	1	\$ 45.90	\$ 45.90

Res Mudflap.

ht

128.50

TOTAL PRICE: 2772 \$ 2,689.40
 LESS 25% \$ 672.35
 SUB TOTAL PRICE: 2079. \$ 2,017.05

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR BODY PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR BODY PANEL GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR WHEEL RIM <i>new</i>	1	\$ 280.00	\$ 280.00
5	REAR WHEEL RIM COVER <i>ht</i>	1	\$ 180.00	\$ 180.00
6	REAR TYRE <i>new</i>	1	\$ 250.00	\$ 250.00

300.

TOTAL: \$ 860.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>600.</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>300.</i>	
3	WIRING CHECK	\$ 50.00	<i>30.</i>	
4	TO APPLY TUFF COAT	\$ 180.00	<i>60.</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50.</i>	
6	TO REMOVE UPHOLSTERY	\$ 150.00	<i>60.</i>	
7	TO REMOVE REAR BODY PANEL GLASS	\$ 120.00	<i>60.</i>	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80.</i>	

TOTAL: \$ 2,750.00

ESTIMATE REPORT

TOTAL PARTS COST:

TOTAL LABOUR COST:

TOTAL REPAIR COST:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation 2,877.05
- To display survey on a "Without Prejudice" basis
- No legal implication of \$ is allowed 2,750.00
- Cost of repair if first must be resurveyed and
- Cost of repair if first must be resurveyed and

Approved by Repairer

1230
Weld: 3609
4/5: 2.5K.
05Days