

# TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO. : 53049097-L

KPT 30A1USLP 318074

ADVANCE COATING SINGAPORE  
BLK 271-C, PUNGGOLWALK, #09-529  
SINGAPORE 823271

DATE ; 11/04/2023

TP Budget Direct.  
Hui Rong

DATE OF ACCIDENT ; 30/03/2023

MODEL ; SSANGYONG / TIVOLI 1.6D STD 6AT 2WD ABS E6FL

CHASSIS NO. ; KPT30A1USLP 318074

## ESTIMATE COST OF REPAIR BILL TO SSANGYONG CAR NO. : SMW9772X

|                                                          |               |               |
|----------------------------------------------------------|---------------|---------------|
| 1 PC REAR BOOTLID <i>Dented</i>                          | S \$ 2,340.00 | <i>1850.</i>  |
| 2 PC REAR BOOTLID ABSORBER <i>xtc m</i>                  | \$ 412.00     | <i>X.</i>     |
| 1 PC REAR BOOTLID LOCK <i>Damaged</i>                    | \$ 428.00     | <i>345.</i>   |
| 1 PC REAR BOOTLID RUBBER <i>ht.</i>                      | \$ 256.00     | <i>✓</i>      |
| 1 PC REAR BOOTLID INNER TRIMBOARD <i>cracked</i>         | \$ 624.00     | <i>510.</i>   |
| 1 PC REAR BOOTLID INNER TRIMBOARD HANDLE <i>xtc m</i>    | \$ 98.00      | <i>X.</i>     |
| 1 PC REAR BOOTLID HANDLE GARNISH <i>cracked</i>          | \$ 126.00     | <i>✓</i>      |
| 1 PC REAR BOOTLID EMBLEM                                 | \$ 96.00      | <i>✓</i>      |
| 1 PC REAR SSANGYONG EMBLEM <i>3 Nec</i>                  | \$ 75.00      | <i>✓</i>      |
| 1 PC REAR TIVOLI EMBLEM                                  | \$ 68.00      | <i>✓</i>      |
| 2 PC REAR TAILLAMP <i>3 x t</i>                          | \$ 1,052.00   | <i>+</i>      |
| 4 PC REAR TAILLAMP CLIP <i>1 m</i>                       | \$ 18.00      | <i>t.</i>     |
| 1 PC REAR END PANEL <i>Repair</i>                        | \$ 780.00     | <i>+</i>      |
| 1 PC REAR END PANEL GARNISH <i>me m</i>                  | \$ 212.00     | <i>+</i>      |
| 4 PC REAR END PANEL GARNISH CLIP <i>me m</i>             | \$ 20.00      | <i>+</i>      |
| 1 PC REAR END PANEL KEYLESS SENSOR <i>cracked</i>        | \$ 192.00     | <i>✓</i>      |
| 1 PC REAR BUMPER (TOP) <i>Dented</i>                     | \$ 880.00     | <i>✓</i>      |
| 2 PC REAR BUMPER SIDE RETAINER <i>xtc m</i>              | \$ 152.00     | <i>X.</i>     |
| 8 PC REAR BUMPER CLIP <i>xtc</i>                         | \$ 40.00      | <i>✓</i>      |
| 2 PC REAR BUMPER REFLECTOR <i>cracked</i>                | \$ 136.00     | <i>✓</i>      |
| 1 PC REVERSE CAMERA <i>Not New</i>                       | \$ 480.00     | <i>S/N X.</i> |
| 1 SET REVERSE SENSOR <i>Dented</i>                       | \$ 200.00     | <i>S/N ✓</i>  |
| 1 PC SPARE WHEEL PANEL (L/H) SPONGE <i>cracked</i>       | \$ 92.00      | <i>✓</i>      |
| 1 PC REAR BUMPER REINFORCEMENT BEAM <i>Dented</i>        | \$ 698.00     | <i>530</i>    |
| 4 PC REAR BUMPER REINFORCEMENT BEAM BRACKET <i>xtc m</i> | \$ 104.00     | <i>X.</i>     |

1 PC REAR LOWER BUMPER *del'd*  
 1 PC REAR LOWER BUMPER THIRD BRAKE LIGHT ASSY *cracked*  
 6 PC REAR LOWER BUMPER CLIP *new*  
 1 SET REAR WINDSCREEN REPAIR KIT *new*  
 1 PC REAR WINDSCREEN SEALANT *new*  
 1 PC REAR NO. PLATE *cracked*  
 1 PC REAR NO. PLATE COVER *del'd*  
 1 PC REAR AIR RESERVOIR CHAMBER TANK *cracked*

\$ ~~726.00~~ *620*  
 \$ 226.00 ✓  
 \$ 30.00 ✓  
 \$ ~~280.00~~ S/N *180(S/N)*  
 \$ 45.00 S/N ✓  
 \$ 26.00 S/N ✓  
 \$ 26.00 S/N ✓  
 \$ 792.00 ✓

LABOUR CHARGE

TO CHECK WIRING *6864*  
 TO SPRAY PAINTING *6177-60*  
 TO REMOVE AND REFIX INTERIOR UPHOLSTERY & CUSHION  
 TO APPLY UNDERCOATING ON THE REPAIRED &  
 REPLACED PANEL FOR RUST PROTECTION  
 TO MEASURE, DRILL THE REPLACED REAR BUMPER,  
 POSITION & REINSTALL REAR REVERSE SENSOR, CONTROL  
 UNIT, REVERSE CAMERA CHECK & TEST FOR FUNCTIONING  
 LABOUR CHARGE TO RESET FAULT CODE AND CARRY OUT  
 DIAGNOSTIC CHECK  
 TO REMOVE AND REFIX REAR WINDSCREEN  
 TO PANEL BEATING, WELDING, REMOVING ALL DAMAGED  
 PARTS & REPLACING OF THE NEW PARTS ETC.

\$ 50.00 *30*  
 \$ ~~1,200.00~~ *650*  
 \$ ~~80.00~~ *40*  
 \$ 80.00 *50*  
 \$ ~~120.00~~ *50*  
 \$ 80.00 *x*  
 \$ ~~150.00~~ *120*  
 \$ ~~950.00~~ *650*

TOTAL :

\$ \$14,440.00

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TK MOTOR WORKSHOP

*total: 8244.60*

*4/s: 6.61c*

*05 Days*

*6.61c*