8/1/23, 3:59 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS23003506/SQY3M4

Date: 01/08/2023

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle SMP245Y

Insured Vehicle No: XE7352C

Date of Loss: 31/03/2023 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMP245Y

 Make & Model:
 KIA CERATO, 1.6 EX (A)
 Engine No:
 G4FGKH741953

 Reg. Date:
 06/09/2019 (Man. Year: 2019)
 Chassis No:
 KNAF3416MK5047599

Colour: White Odometer: 56801 km

Engine Capacity: 1591 cc
Market Value/New Car
Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: NFERA 5 mm Rear Left Side: NFERA 5 mm

Front Right Side: NFERA 5 mm Rear Right Side: NFERA 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,476.80	2,103.20	373.60	15.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	700.00	730.00	51.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,906.80	2,803.20	1,103.60	28.25
+ GST 8.00/8.00% (S\$)	312.54	224.26	88.28	28.25
Nett Amount (S\$)	4,219.34	3,027.46	1,191.88	28.25

INSPECTION

Date of Assignment: 04/04/2023

Date Inspected:

O4/04/2023 Inspected At:

Rispeed Motor Service (HQ)

BLK 3021A UBI ROAD 1 #01-39

Singapore 408715

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/1/23, 3:59 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2023)

Parts: 143 KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMP245Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (R H)	Buckled	1,549.00 FL	*1,277.00 FL
2	1		*DOOR OUTER HANDLE	Missing	69.00 FL	*69.00 FL
3	1		*DOOR LOCK (INTER)	Damaged	400.00 FL	*400.00 FL
4	1		*DOOR LOCK (OUTER)	Damaged	79.00 FL	*79.00 FL
5	1		*POWER WINDOW MOTOR (R H)	Not Necessary	195.00 FL	*- FL
6	1		*DOOR OUTER MOULDING	Dented	129.00 FL	*129.00 FL
7	1		*DOOR HANDLE KNOB	Scratched	38.00 FL	*38.00 FL
8	1		*DOOR GLASS	Cracked	325.00 FL	*325.00 FL
9	1		*GLASS REGULATOR CABLE (FRONT O/S)	Torn	249.00 FL	*249.00 FL
10	1		*FRONT DOOR HANDLE GARNISH	Broken	63.00 FL	*63.00 FL
F=Fra	nchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	3,096.00	2,629.00
			- List Item Discount on L Items 20.00/20.00% (S\$)			525.80
				Total Parts (S\$)	2,476.80	2,103.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	LABOUR CHARGE AS RECOMMENDED FOR REPAIRED & REPLACE AFFECTED AREAS	D New	400.00	200.00		
2	TO PUTTY AND RE-SPRAY PAINT AFFECTED AREAS	New	480.00	200.00		
3	TO SPRAY REAR DOOR & SIDE MIRROR PAINTWORK	New	550.00	300.00		
	Gross Labor	ur Cost (S\$)	1,430.00	700.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >